

Subject to Protective Order - Williams v. Remington

KY	710	71023204	07-01	M5	UPDATED. REAR TAKEDOWN SCREW MISSING.	21072	\$14.00	5 150738
WI	710	71024675	07-01	DID NOT EJECT, DID NOT EXTRACT.	REPLACED EXTRACTOR AND TEST FIRED.	20616	\$41.87	1 131486
MS	710	71023765	07-01	WHSE INSPECTION. BACK PLASTIC SHROUD OF FIRING	WHSE INSPECTION. REPLACED FIRING PIN ASSY	107773	\$15.00	1 DK1396
KY	710	71023156	07-01	PIN ASSY BROKEN.	AND TESTED.	21072	\$14.00	5 157555
KY	710	71023149	07-01	M5		21072	\$14.00	3 124090
KY	710	71024917	07-01	SCREW FOR SCOPE NUT BASE BROKEN IN REC.	REMOVED SCREW AND RETAPPED HOLE AND MODIFIED STOCK, ADDED BOLT	21072	\$19.00	4 150043
KY	710	71021691	07-01	BOLT STOP BROKEN. REC INSERT ASSY BROKEN AT REAR	STOP SPRING.	21072	\$14.00	1 124085
KY	710	71022943	07-01	SCREW.		21072	\$14.00	1 124046
KY	710	71022797	07-01			21072	\$14.00	28 150590
KY	710	71025779	07-01	M5	REPLACED BOLT HANDLE.	21072	\$14.00	11 150596
KY	710	71028422	08-01	M5	UPDATED.	21072	\$14.00	4 150624
KY	710	71028676	08-01	CHECK OUT.	CHECKED OUT.	21072	\$14.00	5 150671
KY	710	71027205	08-01	TRIGGER GUARD. STOCK, BOLT STOP & BOLT STOP	STOCK.	21072	\$14.00	3 150682
KY	710	71025546	08-01	CLIP.	UPDATED.	21072	\$14.00	5 150684
KY	710	71028651	08-01	MAG LATCH BROKEN.	UPDATED.	21072	\$14.00	4 150692
KY	710	71028171	08-01	BOLT STOP & STOCK.	UPDATED.	21072	\$14.00	4 150705
KY	710	71025515	08-01	BOLT STOP.	REPLACED BOLT STOP AND STOCK.	21072	\$14.00	1 150699
NE	710	71027270	08-01	MISFIRES, SAFETY DETENT NOT WORKING.	SHIPPED TO PADUCAH.	21106	\$26.87	5 139219
OR	710	71027691	08-01		SENT TO PADUCAH.	20023	\$26.99	3 110510