

OK	710	71028708	08-01		REINSTALLED BOLT HANDLE.	21047	\$61.22	12 143800
KY	710	71028708	08-01	MAG LATCH PUSHED OUT OF SLOT.	INSTALLED AND REMOVED MAG SEVERAL TIMES.	21072	\$14.00	1 157583
KY	710	71028734	08-01	CUSTOMER REQUEST UPDATE.	UPDATED.	21072	\$14.00	1 124099
KY	710	71028599	08-01	FIRING PIN ASSY WILL NOT STAY IN BOLT.	REPLACED ASSY & TESTED.	21072	\$14.00	5 157554
KY	710	71025627	08-01	BROKEN BOLT STOP.	REPLACED BOLT STOP.	21072	\$14.00	1 157598
KY	710	71028251	08-01	BOLT WILL NOT LOCK INTO CHAMBER.	TESTED, ALL OK.	21072	\$14.00	11 124061
KY	710	71025630	08-01		MAG RELEASE BROKEN.	21072	\$17.50	3 124081
KY	710	71025530	08-01	CUT OUT IN STOCK TOO LONG FROM FACTORY.		21072	\$14.00	5 150033
KY	710	71026483	08-01	FIRING PIN ASSY PLASTIC SHROUD BROKEN.		21072	\$14.00	1 124044
KY	710	71028080	08-01	WILL NOT FEED OR EJECT.	TESTED AND ALL OK.	21072	\$18.50	3 157573
MS	710	71025858	08-01	WAREHOUSE INSPECTION.	WAREHOUSE INSPECTION.	107773	\$15.00	1 DK1486
KY	710	71031208	09-01	FAILS TO FIRE.	TEST FIRED ALL OK.	21072	\$17.00	5 150687
KY	710	71032140	09-01	M5	BOLT BODY.	21072	\$14.00	3 150686
KY	710	71031120	09-01	BOLT STOP.	UPDATED.	21072	\$14.00	4 150709
KY	710	71029593	09-01	TRIGGER GUARD.	STOCK.	21072	\$14.00	1 150704
KY	710	71031475	09-01	WILL NOT FIRE.	TEST FIRED, NO PROBLEMS FOUND.	21072	\$16.25	1 150615
KY	710	71031116	09-01	SCOPE.	SCOPE.	21072	\$14.00	1 150702
KY	710	71031710	09-01	BOLT STOP.	BOLT STOP.	21072	\$14.00	1 150695
OK	710	71031116	09-01	SCOPE BROKEN (LENS).	SENT TO PADUCAH FOR REPAIRS.	21047	\$19.95	27 143704

Subject to Protective Order - Williams v. Remington

BARBER - REM DOCSB0010196

MAE00010112