

AL	710	71032345	09-01	RETURN TO PADUCAH.	RETURNED TO PADUCAH.	21056	\$8.50	1 141700
AL	710	71031134	09-01	RETURN TO PADUCAH.	RETURNED TO PADUCAH.	21056	\$8.50	2 138575
CT	710	71030931	09-01		FORWARDED TO PADUCAH SHOOTERS SUPPLY.	20629	\$10.25	1 151539
CT	710	71030395	09-01		FORWARDED TO PADUCAH SHOOTERS SUPPLY.	20629	\$10.25	1 151554
OH	710	71029920	09-01	TRIGGER GUARD BROKEN.	SENT TO PADUCAH SHOOTERS SUPPLY.	21060	\$23.75	0 SH4570
CT	710	71030400	09-01		FORWARDED TO PADUCAH SHOOTERS SUPPLY.	20629	\$10.25	1 151056
CT	710	71030941	09-01		FORWARDED TO PADUCAH SHOOTERS SUPPLY.	20629	\$10.25	1 151054
KY	710	71031085	09-01	BROKEN BOLT STOP.	REPLACED BOLT STOP.	21072	\$14.00	1 124031
KY	710	71031366	09-01	BOLT WORKS HARD.	KNOCKED BURR OFF BOLT HEAD.	21072	\$14.00	1 124039
KY	710	71030995	09-01	BOLT STOP.	REPLACED BOLT STOP.	21072	\$14.00	4 150552
KY	710	71030609	09-01	PLASTICK SHROUD ON BACK OF FIRING PIN ASSY BROKE.	REPLACED PLASTIC SHROUD ON BACK OF FIRING PIN ASSY.	21072	\$14.00	1 150557
KY	710	71031575	09-01	BOLT WILL NOT CLOSE.	TESTED, ALL CHECKED OK.	21072	\$14.00	6 150751
KY	710	71030395	09-01	BOLT STOP.	REPLACED BOLT STOP.	21072	\$14.00	2 150460
KY	710	71032147	09-01	M5	UPDATED.	21072	\$14.00	6 150472
KY	710	71032345	09-01	M5 AND JAMS.	TESTED WITH NO PROBLEMS.	21072	\$18.00	7 150497
KY	710	71030931	09-01	BOLT STOP BAD, DEFECTIVE SCOPE.	REPLACED BOLT STOP AND SCOPE.	21072	\$14.00	1 150723
KY	710	71032551	09-01	M23	REPLACED MAGAZINE, INSTALLED NEW BOLT BODY.	21072	\$14.00	1 150720
KY	710	71031134	09-01	BOLT HEAD MISSING FROM BOLT.	REPLACED BOLT HEAD.	21072	\$18.00	7 150515
KY	710	71032438	09-01	LEFT BACKER NOT INSTALLED PROPERLY.	ADJUSTED LEFT BACKER AND TESTED.	21072	\$14.00	7 150513

Subject to Protective Order - Williams v. Remington

BARBER - REM DOCSB0010197

MAE00010113