

Subject to Protective Order - Williams v. Remington

KY	710	71032821	10-01	M5	UPDATED.	21072	\$14.00	7 150508
KY	710	71034938	10-01		REPLACED STOCK.	21072	\$14.00	7 150499
KY	710	71034882	10-01	MAG LATCH BROKEN. CUSTOMER WANTED RIFLE TEST	REPLACED STOCK.	21072	\$14.00	1 150573
KY	710	71032624	10-01	FIRE	TEST FIRED, ALL OK. RETURNED TO FACTORY FOR	21072	\$16.25	2 150569
OH	710	71033111	10-01	WONT CHAMBER SHELL FROM CLIP	REPAIR, RETURNED TO	21060	\$44.50	8 SH4827
MS	710	71034968	10-01	WHSE INSPECTION.	WHSE INSPECTION.	107773	\$15.00	1 DK1250
MS	710	71034974	10-01	WHSE INSPECTION.	WHSE INSPECTION.	107773	\$15.00	1 DK1251
OK	710	71033789	10-01	DEFECTIVE MAGAZINE LATCH.	SENT TO PADUCAH.	21047	\$29.95	2 128429
AL	710	71035969	10-01	RETURNED TO PADUCAH.	RETURNED TO PADUCAH.	21056	\$8.50	1 138649
AL	710	71032997	10-01	RETURNED TO PADUCAH.	RETURNED TO PADUCAH.	21056	\$8.50	1 138634
AL	710	71034882	10-01	RETURNED TO PADUCAH.	RETURNED TO PADUCAH.	21056	\$8.50	1 138648
AL	710	71032624	10-01	RETURNED TO PADUCAH.	RETURNED TO PADUCAH.	21056	\$8.50	1 138647
CT	710	71034535	10-01	FORWARD TO PADUCAH.	FORWARDED TO PADUCAH.	20629	\$10.82	1 151090
KY	710	71035453	10-01	MAG LATCH BROKEN.	REPLACED MAG LATCH.	21072	\$14.00	1 157587
KY	710	71034089	10-01		REPLACED BOLT STOP.	21072	\$14.00	2 157594
KY	710	71032690	10-01	STIFF BOLT.	TESTED, ACTION SMOOTHEST I HAVE FELT.	21072	\$14.00	3 157592
KY	710	71032689	10-01	BOLT STOP BROKE.	REPLACED BOLT STOP.	21072	\$14.00	1 157656
KY	710	71033820	10-01	ACTION HARD TO OPEN AND CLOSE.	NEW BOLT HEAD AND BOLT BODY.	21072	\$14.00	1 157655
KY	710	71035216	10-01	BOLT SHROUD BROKEN.	REPLACED BOLT SHROUD.	21072	\$14.00	1 157653