

MS	710	71034231	10-01	WAREHOUSE INSPECTION.	WAREHOUSE INSPECTION.	107773	\$15.00	1 DK1495
OK	710	71035143	10-01		REINSTALLED BOLT HANDLE.	21047	\$60.85	12 142865
CT	710	71036036	11-01		FORWARDED TO PADUCAH SHOOTERS SUPPLY.	20629	\$10.25	1 151094
CT	710	71036406	11-01		FORWARDED TO PADUCAH SHOOTERS SUPPLY.	20629	\$10.25	1 151093
CT	710	71036700	11-01		FORWARDED TO PADUCAH SHOOTING SUPPLY.	20629	\$10.25	1 151626
CT	710	71037574	11-01		FORWARDED TO PADUCAH SHOOTING SUPPLY.	20629	\$10.25	8 151111
KY	710	71036916	11-01	CANNOT GET BOLT OUT OF RIFLE.	DID SAFETY & FUNCTION TESTS, GUN WORKS PERFECT.	21072	\$14.00	4 124008
KY	710	71037334	11-01	M5	UPDATED.	21072	\$14.00	6 124023
KY	710	71037183	11-01	M5	UPDATED.	21072	\$14.00	6 124027
KY	710	71037574	11-01	BOLT BECAME UNCOCKED.	RECOCKED BOLT AND TESTED.	21072	\$14.00	1 124029
KY	710	71039809	11-01	BOLT WORKS HARD.	KNOCKED BURR OFF BOLT HEAD.	21072	\$14.00	1 124040
KY	710	71038742	11-01	FAILS TO FIRE.	REPLACED FIRING PIN ASSY AND TESTED.	21072	\$16.25	4 150553
KY	710	71036700	11-01	GUN FIRES WITHOUT PULLING TRIGGER.	REPLACED REC INSERT ASSY AND TESTED.	21072	\$14.00	1 150532
KY	710	71036464	11-01	BOLT WON'T GO INTO GUN.	COCKED BOLT, TESTED FUNCTION ALL OK.	21072	\$14.00	4 150549
KY	710	71036312	11-01	M5	UPDATED.	21072	\$14.00	1 150579
KY	710	71037188	11-01	BOLT WOULD CLOSE WITH ISS ON.	REPLACED FIRING PIN ASSY. ADJUSTED SPRING ON BOLT STOP LEVER.	21072	\$14.00	2 150570
KY	710	71036733	11-01	CAN'T REMOVE BOLT.		21072	\$14.00	3 150565
OK	710	71037188	11-01	BOLT WILL CLOSE WITH ISS SYSTEM ON.				
AL	710	71036876	11-01	RETURNED TO PADUCAH.	SENT TO PADUCAH.	21047	\$29.95	6 128428
					RETURNED TO PADUCAH.	21056	\$8.50	9 138655

Subject to Protective Order - Williams v. Remington

BARBER - REM DOCSB0010203

MAE00010119