

ST	MODEL	SERIAL #	MFG YR	COMPLAINT	REPAIR	GUNSHOP	TOTAL
MN	597	A2229793	02-81	M9	ADJUSTED EJECTOR TO ENGAGE SHELLS DEEPER, ADJUSTED CLIP LATCH TO HOLD REPLACED HAMMER & TWO NEW MAGAZINES	20017	\$42.69
MN	597	2612572	04-97	M33	REPLACED EXTRACTOR & PLUNGER AND EJECTOR, SAFETY & FUNCTION CHECKED	20954	\$62.27
NY	597	2614537	05-97	M9	REMOVED BURRS AT CHAMBER AREA AND TEST FIRED.	21177	\$20.00
IL	597	2621763	07-97	M24	REPLACED EJECTOR, EXTRACTOR & BOLT GUIDE RAILS AND TEST FIRED.	21028	\$22.00
IL	597	2622793	07-97	M10, M29	REPLACED HOLD OPEN RETAINING SPRING & EJECTOR AND TEST FIRED.	21028	\$32.83
CA	597	2618861	07-97	BOLT WILL NOT RELEASE	REPLACED MAG BOX AND TEST FIRED,	20106	\$36.00
IL	597	2621763	07-97	M24, M33	REMOVED BURRS AT RIM AREA	21028	\$36.03
ARG	597	2624186	07-97		REPLACED MAG BOX ASSY, EXTRACTOR PLUNGER AND EXTRACTOR	104476	\$63.86
MN	597	2626157	08-97	M9	ADJUSTED EJECTOR, SMOOTHED ROUGH EDGES ON BOTTOM OF BOLT AND TEST	20017	\$46.94
MI	597	2628686	08-97	TRIGGER NOT FUNCTIONING.	REPLACED LINK PIN, STAKED HEAD OF PIN AND TEST FIRED.	20108	\$25.00
MD	597	2630934	08-97	BALL WON'T RETAIN EXTRACTOR, MOUTH OF CHAMBER DAMAGED	RETURNED TO FACTORY.	20021	\$10.00
MN	597	2639419	09-97	CLIP LATCH WON'T HOLD.	ADJUSTED EJECTOR AND TEST FIRED.	20017	\$39.40
SC	597	2637818	09-97	M9, M10	CLEANED CHAMBER, REPLACED MAGAZINE AND TEST FIRED.	21044	\$46.66
SC	597	2640308	09-97	MAGAZINE WILL NOT STAY IN GUN.	INSTALLED HOLD OPEN RETURN SPRING & FITTED MAGAZINE RELEASE RETAINING PIN	21044	\$22.40
GA	597	2637457	09-97	BAD EJECTION PROBLEM.	REPAIRED AS NECESSARY.	20300	\$45.00
SC	597	2632379	09-97	RETURN TO FACTORY.	RETURNED TO FACTORY.	20627	\$17.96
IL	597	2632075	09-97		TEST FIRED AND UPDATED.	21028	\$69.46
OH	597	2649115	10-97	EJECTOR PIN CAME OUT MISSING.	REPLACED EXTRACTOR, PLUNGER & SPRING, INSTALLED NEW TYPE EJECTOR,	21060	\$55.59

Subject to Protective Order: Williams v. Remington

BARBER - REM DOCB0010242

MAE00010158