

OH	597	2671971	02-98	MISSING PARTS.	REPLACED MISSING SPRING, EJECTOR, EXTRACTOR, PLUNGER & SPRING.	21060	\$54.37
NY	597	2675839	02-98	FAILS TO FIRE.	REPLACED RIVET, CLEANED & LUBRICATED, FUNCTION & SAFETY CHECKED AND TEST	21036	\$15.50
CT	597	2684271	03-98	M16, M23	EPOXIED LATCH PIN IN PLACE, REPLACED MAG LATCH, SPRING & PIN, CHECKED OVER,	20629	\$50.61
MN	597	2678375	03-98	M9, M23	REPAIRED EJECTOR, ADJUSTED TRIGGER LINKAGE AND TEST FIRED.	20017	\$44.19
NY	597	2689520	04-98	M110	ADJUSTED TRIGGER LINKAGE, REPLACED EJECTOR, SAFETY & FUNCTION CHECKED	21177	\$20.00
GA	597	2688925	04-98	JAMS.	INSTALLED NEW STYLE EJECTOR.	20502	\$12.31
NY	597	2684917	04-98	FAILS TO FIRE.	REPLACED BROKEN BOLT HANDLE SPRING & RIVET AND FIRING PIN, SAFETY & FUNCTION	21036	\$37.64
LA	597	2684822	04-98	WOULD NOT EXTRACT.	REPLACED EXTRACTOR, PLUNGER & SPRING AND TESTED	21049	\$19.30
MN	597	2691222	04-98	M10	REPLACED EXTRACTOR.	20954	\$33.88
GA	597	2692439	05-98	ACCURACY.	FOUND REAR MOUNT HAD BEEN LOWERED ALL THE WAY, ADJUSTED REAR SIGHT.	20300	\$40.00
NE	597	2696124	05-98	M9, M23, M27	POLISHED CHAMBER & DEBURRED, CLEANED AND TEST FIRED.	21106	\$55.85
OR	597	2693709	05-98	BROKEN EXTRACTOR.	REPLACED EXTRACTOR, EJECTOR & SPRING.	20023	\$47.81
OH	597	2693559	05-98	SHOOTS INCORRECTLY, SOMETIMES SHOOTS AUTO	REPLACED TRIGGER HOUSING & MAGAZINE, CLEANED, CHECKED AND TEST FIRED.	21060	\$94.18
MN	597	2692447	05-98	M5, M9	REPLACED WEAK BOLT HANDLE, ADJUSTED EJECTOR TO ENGAGE SHELLS DEEPER AND	20017	\$43.10
NY	597	2699794	06-98	M9	ADJUSTED ACTION TIGHTNESS, REPLACED EJECTOR, SAFETY & FUNCTION CHECKED	21177	\$20.00
OH	597	2698903	06-98	DOES NOT FIRE RIGHT, CHECK EVERYTHING, ACTION, FIRING PIN	INSTALLED NEW TYPE EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$59.98
ARG	597	2699846	06-98		REPLACED FIRING PIN & SPRING.	104476	\$66.80
VT	597	2911843M	06-98	JAMS.	REPLACED MAGAZINE & EJECTOR, POLISHED & DEBURRED CHAMBER & BOLT.	20803	\$116.71
MS	597	2699487	06-98	WAREHOUSE INSPECTION.	WAREHOUSE INSPECTION.	107773	\$15.00