

OK	597	2707417	07-98		ADJUSTED BOLT HANDLE SPRING, SAFETY AND TEST FIRED.	21047	\$27.72
VA	597	2914263M	07-98	WON'T EXTRACT, PIECES OF MAG BLEW OUT.	REMOVED BOLT, REPLACED EXTRACTOR, PLUNGER & SPRING, REASSEMBLED.	20960	\$53.34
IL	597	2706040	07-98	M24, M23	REPLACED EJECTOR, EXTRACTOR, PLUNGER & SPRING AND TEST FIRED.	21028	\$25.77
NY	597	2916690M	08-98	M138	ADJUSTED ACTION TIGHTNESS, SAFETY & FUNCTION CHECKED AND TESTED.	21177	\$20.00
CT	597	2700151	08-98	M25	INSTALLED MODIFIED EJECTOR, CHECKED OVER, CLEANED & OILED, SAFETY & REPLACED BOLTS & SCREWS, CHECKED	20629	\$49.53
CT	597	2654694	08-98	BED STOCK.	OVER, CLEANED & OILED, SAFETY & REPLACED EXTRACTOR, SPRING AND PLUNGER.	20629	\$43.93
VA	597	2711030	08-98	WON'T EXTRACT.	REPLACED OPERATING HANDLE SPRING & SPRING RIVET, INSTALLED NEW STYLE	20960	\$50.11
OK	597	2708309	08-98	M9		21047	\$36.32
IL	597	2916015M	08-98		REPLACED TRIGGER HOUSING ASSY.	21028	\$49.22
IL	597	2712239	09-98		METAL CLIP	21028	\$21.53
IL	597	2712239	09-98	M24, M33	REPLACED EJECTOR & MAG BOX, REMOVED BURRS AT CHAMBER AREA AND TEST FIRED.	21028	\$39.86
NC	597	2918472M	10-98	M5	DRILLED OUT BOLT HANDLE RET SPRING & RIVET AND INSTALLED NEW ONE.	21102	\$38.20
AL	597	2918083M	10-98	M10	HONED CHAMBER.	21056	\$22.50
CAN	597	2918987M	10-98	CARTRIDGE JAMMING IN MAG, WILL NOT EXTRACT CART FROM	POLISHED CHAMBER, REPLACED DEFECTIVE MAG, TESTED, CLEANED AND OILED.	20630	\$34.66
VA	597	2717408	10-98	WON'T SHOOT STRAIGHT, SIGHTS WON'T ADJUST FAR ENOUGH.	REPLACED BBL, REAR SIGHTS & SCREWS AND TESTED.	20960	\$127.44
IA	597	2919564M	10-98	M10	REPLACED BROKE EXT.	20308	\$30.10
LA	597	2917347M	10-98	M9, M10, M23	REPLACED EXTRACTOR, SPRING & PLUNGER, REPLACED MAGAZINE AND	20204	\$40.65
IL	597	2917942M	10-98	M33	REPLACED MAGAZINE & HOLD OPEN RETURN SPRING AND TEST FIRED.	21028	\$48.30
CAN	597	2720906	11-98	ACCURACY PROBLEM.	INSTALLED NEW BBL, DRILLED & TAPPED HOLE ORIFICES AND TESTED AT RANGE.	21040	\$98.90