MAE
0
0
0
\mathbf{H}
0
\vdash
g
ίIJ

19.9							
				e Highesternitis with accommon to the activities and the activities activities and the activities and the activities and the activities activities and the activities activities activit	INSTALLED NEW STYLE EJECTOR, SAFETY &		
OK.	597	2745689	104-99	M9	TEST FIRED.	21047	\$35.25
		303	3337773	and formation a commentation for the comment of the	REPLACED BOLT, EXTRACTOR PLUNGER		
" ARG	S97	2747392	04-99	· ///	AND EXTRACTOR.	104476	\$119.10
			<i>8</i>	W. W	REPLACED TRIGGER HOUSING ASSY & 2 ISS		
OK	597	2747598	104-99		KEYS, SAFETY & TEST FIRED.	21047	\$76.05
	779				SHIPPED GUN BACK TO CUSTOMER AFTER		
ΤX	597	2744522	104-99	BOLT BURNED A HOLE THRU IT.	FULL INSPECTION SHOWED NO PROBLEMS.	21123	\$12.00
		3.48	21		CHECKED OVER, CLEANED & OILED, SAFETY		
CT	597	2934333M	105-99	M23	& FUNCTION TESTED. REPLACED MAG ASSY.	20629	\$48.79
			1 2000	1 ////	INSTALLED NEW STYLE EJECTOR AND TEST		
KY	597	2750170	105-99	GUNIJAMS.	FIRED.	21072	\$16.00
					REMOVED BURRS AT CHAMBER, REPLACED		
IL	597	2749684	105-99	⊨M10, M24	EJECTOR AND TEST FIRED.	21028	\$25.16
		******	1	****	REPLACED EJECTOR, REMOVED BURRS AT	04000	
IL	597	2750114	105-99	M10, M24	CHAMBER AREA	21028	\$33.56
	507	0740744	05.00	FAILS TO EXTRACT, JAMS & STOCK		400440	F00.00
CO	597	2749741	∤05-99	SCRATCHED ON FIRST RETURN.	SENT TO FACTORY. REPLACED BOLT HANDLE BOLT SPRING &	106412	\$30.00
NY	597	2751455	106-99	l ⊧ M145	RIVET AND EJECTOR, SAFETY & FUNCTION	21177	\$20.00
INT	281	2791400	100-ลล	FIRED SHELL WITHOUT BEING	REPLACED EJECTOR, SAFETT & FUNCTION	2 2144	\$20.00
MI	597	2751188	,06-99	CLOSED.	PLUNGER AND SPRING	21031	\$41.29
1951	357	2731100	{00-35	OLOGED.	REPLACED EJECTOR, SAFETY & FUNCTION	2,00	\$41.£3
NY	597	2753537	06-99	M137	CHECKED AND TESTED.	21177	\$20.00
141	001	2100001	300 00	ENTINE CONTRACTOR CONT	REPLACED TRIGGER HOUSING ASSY.		
IL	597	2755230	.06-99		EXTRACTOR & MAG CLIP.	21028	\$79.39
	u 5.	2100200	10000	<u> </u>	Ziriri da la	# - · · · · · #	
co	597	2752646	06-99	¹ M9	SENT TO FACTORY (SECOND TIME IN).	106412	\$30.00
			**************************************	. HTTELE ACTION A. A. S. S. V. I R. S.	SAFETY & FUNCTION CHECKED AND		1,777,770
NY	597	2937919M	07-99	M137	TESTED, NO FAULT FOUND.	21177	\$20.00
				A	REPLACED EXTRACTOR ASSY AND TEST		
ΤX	597	2937787M	¹ 07-99	EXTRACTOR ASSY MISSING.	FIRED.	21069	\$27.11
			£	WON'T EXTRACT, LEAVES SHELL IN	REPLACED EXTRACTOR, SPRING AND		
VA	597	2937104M	¹ 07-99	CHAMBER, EXTRACTOR MISSING.	PLUNGER.	20960	\$51.11
			7	The state of the s	ment and the control of the control		
CA	597	2758888	08-99	LEJECTION PROBLEMS.	INSTALLED EJECTOR UPGRADE.	20801	\$13.50
			1		INSTALLED NEW EJECTOR & MAGAZINE,		
CT	597	2758142	08-99	M23	CHECKED OVER, CLEANED & OILED, SAFETY	20629	\$51.76