

OK	597	2775118	11-99	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.95
UT	597	2772928	11-99	BURR AT CHAMBER MOUTH.	POLISHED OFF BURR AND TEST FIRED.	107415	\$11.50
NY	597	2774871	11-99	M142	PERFORMED SAFETY & FUNCTION TESTS.	21177	\$20.00
KY	597	2774437	11-99	M23	REASSEMBLED MAG LATCH, REPLACED EJECTOR, SAFETY & FUNCTION CHECKED	21177	\$20.00
NY	597	2773555	11-99	M137	REPAIRD MAG LATCH ASSY AND TESTED.	20309	\$21.50
WI	597	2772835	11-99	M9	REPLACED EJECTOR, ADJUSTED ACTION TIGHTNESS, SAFETY & FUNCTION CHECKED	21177	\$20.00
IL	597	2775129	11-99	M15, M24, M33	REPLACED EJECTOR.	20616	\$15.17
MI	597	2775561	11-99		REPLACED MAG BOX, LATCH & EJECTOR.	21028	\$54.62
OH	597	2775227	11-99	CLIP WON'T STAY IN.	REPLACED TRIGGER ASSY AND TEST FIRED.	21054	\$52.99
VA	597	2775513	11-99	WON'T EXTRACT, MAG WON'T STAY TOGETHER, MAG LATCH BROKE.	REPLACED TRIGGER ASSY, CLEANED, CHECKED AND TEST FIRED	21060	\$80.48
VA	597	2775521	11-99	T SAFETY STUCK, BUFFER CAME OUT OF ASSY, LOCKED UP GUN.	REPLACED TRIGGER ASSY, EXTRACTOR & SPRING AND MAGAZINE.	20960	\$116.24
CO	597	2773555	11-99	M23	REPLACED TRIGGER ASSY. REINSTALLED BUFFER.	20960	\$79.49
CO	597	2775050	11-99	MAG WON'T STAY IN GUN.	RETURNED TO FACTORY, TEST FIRED WHEN BACK.	106412	\$18.00
CO	597	2772529	11-99	FAILS TO FEED.	RETURNED TO FACTORY.	106412	\$15.00
NY	597	2775856	12-99	M110	RETURNED TO FACTORY.	106412	\$15.00
NY	597	2945286M	12-99	M137	ADJUSTED ACTION TIGHTNESS, REPLACED EJECTOR, SAFETY & FUNCTION CHECKED	21177	\$20.00
AL	597	2775633	12-99	JAMS.	ADJUSTED ACTION TIGHTNESS, SAFETY & FUNCTION CHECKED AND TESTED.	21177	\$20.00
OH	597	2946959M	12-99	JAMS.	ADJUSTED EJECTOR.	21056	\$22.00
OH	597	2946961M	12-99	CLEAN AND CHECK.	CLEANED, CHECKED AND TEST FIRED.	21060	\$30.75
					CLEANED, CHECKED AND TEST FIRED.	21060	\$30.75

Subject to Protective Order - Williams v. Remington

BARBER - REM DOCSB0010249

MAE00010165