

CT	597	2787337	04-00	M8	REPLACED OPERATING HANDLE, SPRING & RIVET, CHECKED OVER, CLEANED & OILED,	20629	\$47.49
OH	597	2786592	04-00	BROKEN STOCK.	REPLACED STK ASSY, INSTALLED NEW	21060	\$86.49
MN	597	2790566	05-00	M23	STYLE EJECTOR & REPLACED REAR SIGHT,	20017	\$41.51
OK	597	2786870	05-00	M1, M9	ADJUSTED EJECTOR TO ENGAGE SHELLS	21047	\$27.35
AL	597	2789191	05-00	M9	DEEPER, ADJUSTED CLIP LATCH SPRING	21056	\$22.50
TX	597	2790318	05-00	DEFECTIVE.	ADJUSTED EJECTOR, TIGHTENED LOOSE	21087	\$36.19
CAN	597	2758132	05-00	RECEIVER CRACKED, INACCURATE.	SIGHT, BORESIGHTED, SAFETY & TEST	21040	\$73.18
CA	597	2791164	05-00	MAG WILL NOT STAY IN GUN.	TESTED.	20106	\$32.15
MN	597	2789992	05-00	SAFETY FUNCTION INCORRECT.	REINSTALLED LATCH SPRING & REPLACED	20017	\$43.38
ARG	597	2945069M	05-00		EJECTOR AND TEST FIRED.	104476	\$76.79
CAN	597	2732109	05-00	JAMMING.	REPAIRED SAFETY & PLUNGER TO OPERATE	20957	\$54.10
CAN	597	2750909	05-00	JAMMING, FIRING PIN NOT HITTING	SMOOTHLY AND TEST FIRED.	20957	\$53.60
CAN	597	2791654	05-00	HARD.	REPLACED EJECTOR AND TESTED.	21096	\$73.39
ARG	597	2945071M	05-00	M9, M23	REPLACED MAG BOX ASSY & HOLD OPEN	104476	\$92.13
CAN	597	2783952	05-00	M23	RETURN SPRING AND TEST FIRED.	268418	\$42.63
CAN	597	2791532	05-00	SAFETY WOULD NOT ENGAGE.	REPLACED MAG BOX ASSY AND FRONT	268418	\$45.66
MI	597	2790039	05-00		SIGHT & SCREW.	21054	\$21.56
GA	597	2793154	06-00	M9	UPDATED TO NEW EJECTOR AND TEST	20300	\$50.00
CO	597	2795322	06-00	M23	FIRED.	106412	\$30.70
					CLEANED UP GUMMED UP SUBSTANCE ON		
					BUFFER BOLT, REINSTATED BUFFER AND		
					FUNCTION CHECKED, ORDERED NEW		
					MAGAZINE AND TEST FIRED.		

Subject to Protective Order - Williams v. Remington

BARBER - REM DOCSB0010252

MAE00010168