

MI	597	2794851	06-00	M9	REPLACED EJECTOR AND TESTED.	20108	\$57.17
NY	597	2795587	06-00	M135	REPLACED TRIGGER HOUSING ASSY, SAFETY & FUNCTION CHECKED AND	21177	\$20.00
NY	597	2784071	07-00	M138	ADJUSTED ACTION TIGHTNESS, REPLACED EJECTOR, SAFETY & FUNCTION CHECKED	21177	\$20.00
NY	597	A2612913	07-00	M110	ADJUSTED ACTION TIGHTNESS, REPLACED EJECTOR, SAFETY & FUNCTION CHECKED	21177	\$20.00
OR	597	2798686	07-00	JAMS	INSTALLED NEW STYLE EJECTOR, TESTED AND CLEANED.	20023	\$40.28
OK	597	A2615051	08-00	M9	REPLACED BOLT SPRING RIVET, BOLT HANDLE SPRING & EJECTOR, SAFETY &	21047	\$31.20
NY	597	2960212M	08-00	M145	REPLACED BOLT SPRING, BOLT SPRING RIVET & BOLT HANDLE, SAFETY & FUNCTION	21177	\$20.00
OR	597	A2621688	09-00	NOT STAYING OPEN ON EMPTY MAG.	ADJUSTED MAG LATCH.	20023	\$18.00
SD	597	A2620378	09-00	M9	FUNCTIONS & SAFETY CHECKED, TEST FIRED.	20510	\$25.91
OK	597	A2621890	09-00	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$18.73
OK	597	A2618999	09-00	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.58
MN	597	A2620562	09-00	FIRES WHEN SAFETY IS ON.	REPAIRED TRIGGER TO ENGAGE DEEPER AND TEST FIRED.	20017	\$41.40
CT	597	A2620116	09-00	M25	REPLACED EJECTOR, CHECKED OVER, CLEANED & OILED, SAFETY & FUNCTION	20629	\$42.98
AL	597	A2618075	09-00	M10	REPLACED EXTRACTOR AND PLUNGER.	21056	\$23.74
OK	597	A2621676	09-00	M9, M15	REPLACED MAG BOX ASSY, INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$38.36
AL	597	A2621465	09-00	SENT TO FACTORY.	SENT TO FACTORY.	21056	\$8.50
OR	597	A2618995	09-00	CARTRIDGE EXPLODED IN CHAMBER.	SENT TO FACTORY.	20023	\$25.56
ID	597	A2620989	09-00	FEED, EJECTION PROBLEMS, BOLT HANDLE POPS OUT.	TIGHTENED UP BOLT HANDLE, ADJUSTED EJECTOR FURTHER INTO BOLT FACE AND	20800	\$29.00
MS	597	A2615517	09-00	WAREHOUSE INSPECTION.	WAREHOUSE INSPECTION.	107773	\$15.00

Subject to Protective Order - Williams v. Remington

BARBER - REM DOCSB0010253

MAE00010169