

AL	597	A2624722	10-00	M9	ADJUSTED EJECTOR.	21056	\$22.00
OR	597	A2623910	10-00	UPDATE EJECTOR.	CHECKED EJECTOR AND TESTED.	20023	\$29.36
SD	597	A2624741	10-00	M33	FUNCTIONS & SAFETY CHECKED, TEST FIRED. REPLACED MAGAZINE.	20510	\$32.47
SD	597	A2615215	10-00	SIGHT PART MISSING.	FUNCTIONS & SAFETY CHECKED, TEST FIRED. REPLACED REAR SIGHT ADJUSTURE	20510	\$30.50
AL	597	A2626550	10-00	M10	HONED CHAMBER.	21056	\$22.50
AL	597	A2626766	10-00	M10	HONED CHAMBER.	21056	\$22.50
IL	597	A2623168	10-00	M5	INSTALLED NEW SPRING & RIVET. INSTALLED NEW STYLE EJECTOR.	21028	\$23.86
OK	597	A2626087	10-00	M9	REPLACED SPRING, BOLT HANDLE & RIVET, INSTALLED NEW STYLE EJECTOR, TEST FIRED AND SAFETY CHECKED.	21047	\$31.20
OK	597	A2626756	10-00	M9		21047	\$35.96
AL	597	A2618148	10-00	M10	POLISHED CHAMBER.	21056	\$22.50
IL	597	A2625240	10-00	SIGHTS DRILLED OFF CENTER.	REPLACED BBL AND TEST FIRED	21028	\$64.06
GA	597	A2622818	10-00	NEEDS NEW HANDLE.	REPLACED BOLT HANDLE AND EJECTOR. REPLACED BOLT HANDLE, SPRING & RIVET.	20502	\$21.84
CT	597	A2623971	10-00	M5	CHECKED OVER, CLEANED & OILED, SAFETY	20629	\$48.93
NY	597	A2624315	10-00	M146	REPLACED BOLT SPRING, BOLT SPRING RIVET, REPLACED EJECTOR, SAFETY & REPLACED EJECTOR & MAG BOX, REMOVED BURRS AT CHAMBER AREA AND TEST FIRED.	21177	\$20.00
IL	597	A2625782	10-00		REPLACED EJECTOR AND BOLT ASSY AND TEST FIRED.	21028	\$40.74
KY	597	A2624009	10-00	WON'T CYCLE OR EJECT.	REPLACED EJECTOR AND MAG BOX, TEST FIRED.	21072	\$69.84
IL	597	A2625783	10-00			21028	\$30.74
KY	597	A2624009	10-00	M9	REPLACED EJECTOR AND TEST FIRED.	21072	\$21.23
CAN	597	A2623054	10-00	M9	REPLACED EJECTOR AND TESTED.	268418	\$13.03