

NY	597	A2617397	10-00	M137	REPLACED EJECTOR, SAFETY & FUNCTION CHECKED AND TESTED.	21177	\$20.00
NY	597	A2625649	10-00	M137	REPLACED EJECTOR, SAFETY & FUNCTION CHECKED AND TESTED.	21177	\$20.00
CAN	597	A2623208	10-00	M9	REPLACED EJECTOR.	268418	\$13.03
AL	597	A2625159	10-00	WON'T FIRE, FIRING PIN RETAINING PIN FELL OUT.	REPLACED FIRING PIN RETAINING PIN.	21056	\$24.10
VA	597	A2623424	10-00	BROKEN CLIP.	REPLACED MAG BOX ASSY.	21080	\$6.70
OK	597	A2617735	10-00	M9, M15, M23	REPLACED MAGAZINE, EJECTOR, EXTRACTOR, PLUNGER AND SPRING, REPLACED MAGAZINE, INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$44.56
OK	597	A2616124	10-00	M9	REPLACED MAGAZINE, INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$41.28
OR	597	A2620280	10-00	SIGHT MISSING.	REPLACED MISSING SIGHT.	20023	\$34.05
OK	597	2799085	10-00	M9	REPLACED RIVET, SPRING & INSTALLED NEW STYLE EJECTOR, SAFETY & TEST	21047	\$32.77
OR	597	A2613880	10-00	M28	REPLACED TRIGGER HOUSING ASSY.	20200	\$68.07
CAN	597	A2623777	10-00	M9	REPLACED WITH N/S EJECTOR.	268418	\$21.68
AL	597	A2615823	10-00	SENT TO FACTORY.	SENT TO FACTORY.	21056	\$8.50
CAN	597	A2623223	10-00	M9	STRIPPED DOWN, EXCHANGED EJECTOR, REBUILT AND TESTED.	268418	\$13.03
OK	597	A2616242	10-00	M1	TIGHTENED LOOSE REAR SIGHT, ADJUSTED SIGHTS TO ALIGN WITH BORE,	21047	\$23.03
OK	597	A2615850	10-00	M1, M9	TIGHTENED LOOSE SIGHT, INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.95
OR	597	A2624645	10-00	GUN CLIP JAMS.	UPDATED EJECTOR, CLEANED AND TESTED.	20023	\$54.28
MS	597	A2620275	10-00	WHSE INSPECTION.	WHSE INSPECTION.	107773	\$15.00
AL	597	A2628726	11-00	JAMS.	ADJUSTED EJECTOR.	21056	\$22.00
AL	597	A2628461	11-00	M9	ADJUSTED EJECTOR.	21056	\$22.50

Subject to Protective Order - Williams v. Remington

BARBER - REM DOCSB0010255

MAE00010171