

MT	597	A2627343	11-00	M23	ADJUSTED FEEDING AND TEST FIRED.	20113	\$30.25
IL	597	A2627833	11-00	M19	BLUED BBL AND PUT BACK TOGETHER.	21028	\$35.00
LA	597	A2628974	11-00	M9, M23	CLEANED & POLISHED CHAMBER, ADJUSTED EJECTOR.	20204	\$26.25
OR	597	A2631157	11-00	MISFIRES	CLEANED, UPDATED EJECTOR AND TESTED. FUNCTIONS & SAFETY CHECKED, TEST FIRED.	20023	\$43.67
SD	597	A2628736	11-00	M9		20510	\$25.70
AL	597	A2627133	11-00	M10	HONED CHAMBER.	21056	\$22.50
AL	597	A2628613	11-00	M10	HONED CHAMBER	21056	\$22.50
KY	597	A2627833	11-00	NOT FEEDING OR EJECTING ALL THE TIME.	INSTALLED NEW STYLE EJECTOR & REPLACED MAG AND TEST FIRED.	21072	\$26.70
OK	597	A2631087	11-00	M1, M9	INSTALLED NEW STYLE EJECTOR, BORESIGHTED, SAFETY & TEST FIRED.	21047	\$29.95
OK	597	A2627457	11-00	M9	INSTALLED NEW STYLE EJECTOR, REPLACED RIVET, BOLT SPRING & SPRING	21047	\$31.69
OK	597	A2628733	11-00	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$35.25
OK	597	A2630609	11-00	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$34.95
OK	597	A2628320	11-00	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.95
OK	597	A2628556	11-00	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.53
MI	597	A2628379	11-00	JAMS.	POLISHED CHAMBER, INSTALLED NEW STYLE EJECTOR AND TESTED.	21030	\$22.23
CT	597	A2629916	11-00	M23	REAMED & POLISHED CHAMBER, CHECKED OVER, CLEANED & OILED, SAFETY &	20629	\$48.32
MN	597	A2629512	11-00	NOT FEEDING. EXTR ASSY MISSING, BOLT ASSY	REFIT EXTRACTOR AND TESTED.	20954	\$26.00
TN	597	A2630163	11-00	DEFECTIVE.	REPLACED BOLT & FIT NEW EXTRACTOR ASSY AND TEST FIRED.	21052	\$67.29
CA	597	A2630176	11-00	NOT EJECTING.	REPLACED BROKEN EJECTOR AND TEST FIRED.	20112	\$23.75

Subject to Protective Order - Williams v. Remington

BARBER - REM DOCSB0010256

MAE00010172