

OK	597	A2631081	11-00	M9	REPLACED BROKEN TRIGGER HOUSING ASSY, INSTALLED NEW STYLE EJECTOR,	21047	\$71.19
AL	597	A2627521	11-00		REPLACED CLIP ASSY, REINSTALLED EXTRACTOR.	21056	\$30.78
OK	597	A2631085	11-00	M9	REPLACED DEFECTIVE FIRING PIN.	21047	\$41.80
CA	597	A2630107	11-00	M23	INSTALLED NEW STYLE EJECTOR, SAFETY & REPLACED EJECTOR & REMOVED BURRS FROM CHAMBER AND TEST FIRED.	20106	\$32.15
FL	597	A2628711	11-00	WONT EJECT	REPLACED EJECTOR WITH NEW STYLE AND TEST FIRED.	20603	\$14.70
NY	597	A2629802	11-00	M137	REPLACED EJECTOR, ADJUSTED ACTION TIGHTNESS, SAFETY & FUNCTION CHECKED	21177	\$20.00
NY	597	A2630319	11-00	M110	REPLACED EJECTOR, PLACED HOLD OPEN SPRING IN PROPER POSITION, SAFETY &	21177	\$20.00
NY	597	A2630840	11-00	M137	REPLACED EJECTOR, SAFETY & FUNCTION CHECKED AND TESTED.	21177	\$20.00
OK	597	A2628448	11-00	M9, M15, M23	REPLACED MAGAZINE & EJECTOR, SAFETY & TEST FIRED.	21047	\$38.73
IL	597	A2630909	11-00	M10, M33	REPLACED MAGAZINE AND EJECTOR	21028	\$44.16
AL	597	A2629932	11-00	TRIGGER ASSY CRACKED CAUSING MALFUNCTION.	REPLACED TRIGGER ASSY.	21056	\$61.73
NY	597	A2633028	12-00	M137	ADJUSTED ACTION TIGHTNESS, REPLACED EJECTOR, SAFETY & FUNCTION CHECKED	21177	\$20.00
MN	597	A2633014	12-00	M10	ADJUSTED TRIGGER GROUP TO OPERATE CORRECTLY, ADJUSTED EJECTOR TO	20017	\$51.47
MI	597	A2632898	12-00	JAMS.	CLEANED, POLISHED CHAMBER AND TESTED.	21030	\$34.90
OR	597	A2632282	12-00	WON'T FEED PROPERLY, JAMS.	CLEANED, UPDATED EJECTOR AND TESTED.	20023	\$39.84
NY	597	A2632820	12-00		FUNCTION TESTED, REPLACED EJECTOR.	20312	\$30.81
AL	597	A2631420	12-00	M10	HONED CHAMBER.	21056	\$22.50
OK	597	A2632367	12-00	M23	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$18.73
OK	597	A2632284	12-00	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.58