

GUN EXAMINATION REPORT NUMBER: MODEL: 700 ADLGENERAL CONDITION: NEWR # : 07070OUTSIDE WORK: TRIGGER ENGAGEMENT SCREWDATE: 4-23-71SEAL REMOVED.FROM: LLOYD Co.FIRED AMMO TYPE: -LITTLE ROCK, ARK.& CONDITION: ASSEMBLER 65GUN # : 6266361PROOF: R.I.P.-E INSP.: 73 TEST: 87CODE: WS = 8/69HEADING: O.K.GA./CAL.: 22-250BREACH OPENING: -CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K.APPROVED: CHAMBER: O.K.APPROVED: TEST: NOAPPROVED:

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: TRIGGER CONNECTOR BROKEN. TRIGGER SPRING MISSING.TRIGGER ENGAGEMENT SCREW OUT OF ADJUSTMENT.COMPLAINT: "LEVER IN TRIGGER HOUSING BROKEN"INCIDENT: -COMMENTS: APPARENTLY A DEFECTIVE TRIGGER CONNECTOR WAS USED.PLAINTIFF'S
EXHIBIT

3278