

AL	597	A2636501	01-01	M10, M24	HONED CHAMBER.	21056	\$22.00
AL	597	A2637049	01-01	M10	HONED CHAMBER.	21056	\$22.50
OR	597	A2632264	01-01	BOLT LEVER BROKE.	INSTALLED BOLT HANDLE SPRING & RIVET. UPDATED WITH NEW STYLE EJECTOR AND	20023	\$33.23
KY	597	A2636408	01-01	ACTION SQUEAKS.	INSTALLED NEW EJECTOR AND TEST FIRED.	21072	\$26.23
KY	597	A2636814	01-01	JAMS.	INSTALLED NEW EJECTOR AND TEST FIRED.	21072	\$21.23
KY	597	A2636399	01-01	JAMS.	INSTALLED NEW STYLE EJECTOR AND TEST FIRED.	21072	\$21.23
KY	597	A2636541	01-01	JAMS.	INSTALLED NEW STYLE EJECTOR AND TEST FIRED.	21072	\$21.23
MI	597	A2635965	01-01	M9	INSTALLED NEW STYLE EJECTOR AND TEST FIRED.	21019	\$40.25
OH	597	A2633824	01-01	MISSING BOLT LEVER.	INSTALLED NEW STYLE EJECTOR. REPLACED BOLT ASSY & NEW BOLT	21060	\$91.07
OK	597	A2637742	01-01	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.58
OK	597	A2635978	01-01	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$30.25
OH	597	A2635208	01-01	SHELL CASING GETS JAMMED WHEN EJECTED, ACTION DOESNT	INSTALLED NEW TYPE OF EJECTOR. CLEANED, CHECKED AND TEST FIRED.	21060	\$42.48
AL	597	A2637451	01-01	M23, M24	RECUT CHAMBER.	21056	\$22.50
AL	597	A2633396	01-01	M24	REMOVED BURR.	21056	\$22.50
AL	597	A2631731	01-01	M23, M24	REPLACED CLIP ASSY, REMOVED BURR FROM CHAMBER.	21056	\$31.28
MI	597	A2635848	01-01	M9	REPLACED EJECTOR AND TEST FIRED.	20108	\$46.17
KY	597	A2636516	01-01	M9	REPLACED EJECTOR WITH NEW STYLE. CLEARED ACTION AND TEST FIRED.	21072	\$38.73
NY	597	A2636805	01-01	M137, M940	REPLACED EJECTOR, ADJUSTED HOLD OPEN, SAFETY & FUNCTION CHECKED AND	21177	\$20.00
AL	597	A2637709	01-01	JAMS AFTER FIRING.	REPLACED EJECTOR.	21056	\$25.00

Subject to Protective Order - Williams v. Remington

BARBER - REM DOCSB0010259

MAE00010175