

Subject to Protective Order - Williams v. Remington

CAN	597	A2635075	01-01	M9	REPLACED EJECTOR.	268418	\$13.03
CAN	597	A2635340	01-01	M9	REPLACED EJECTOR.	268418	\$21.68
CAN	597	A2635366	01-01	M9	REPLACED EJECTOR.	268418	\$13.03
CAN	597	A2635297	01-01	M9	REPLACED EJECTOR.	268418	\$13.03
CAN	597	A2635021	01-01	M9	REPLACED EJECTOR.	268418	\$13.03
CT	597	A2636880	01-01	M9, M10, M23	REPLACED MAG, LATCH, SPRING & PIN, CLEANED AND OILED.	20629	\$50.61
CAN	597	A2635524	01-01	WON'T FEED PROPERLY, MISFIRES & STOVEPIPES.	REPLACED NEW STYLE EJECTOR AND MAGAZINE.	268418	\$44.44
OR	597	A2632264	01-01	MISSING SCREW ON TAB	REPLACED PLUG SCREW.	20023	\$30.33
AL	597	A2633714	01-01	SENT TO FACTORY.	SENT TO FACTORY.	21056	\$8.50
MN	597	A2642065	02-01	M9	ADJUSTED EJECTOR TO ENGAGE SHELLS DEEPER AND TEST FIRED.	20017	\$41.64
NY	597	A2638371	02-01	CAN'T PUT BOLT HANDLE IN GUN.	ADJUSTED OPERATING HANDLE BOLT SPRING, FUNCTION & SAFETY CHECKED AND	21036	\$24.00
CAN	597	A2639173	02-01	M9	EXCHANGED N/S EJECTOR.	268418	\$13.03
MI	597	A2638276	02-01	JAMS.	INSTALLED & ADJUSTED NEW EJECTOR.	21054	\$49.23
CT	597	A2638247	02-01	M16, M33	INSTALLED MODIFIED EJECTOR, CHECKED OVER, CLEANED & OILED, SAFETY &	20629	\$51.78
CT	597	A2638216	02-01	M25	INSTALLED MODIFIED EJECTOR, CHECKED OVER, CLEANED & OILED, SAFETY &	20629	\$42.98
OK	597	A2641360	02-01	M1, M9	INSTALLED NEW STYLE EJECTOR, ADJUSTED SIGHTS TO ALIGN WITH BORE.	21047	\$29.58
NE	597	A2640484	02-01	M9	POLISHED CHAMBER, REPLACED MAGAZINE.	21106	\$60.88
TX	597	A2640180	02-01	WON'T FEED OR EJECT.	REFIT SEAR SPRING, INSTALLED EJECTOR AND TEST FIRED, CHECKED ALL FUNCTIONS	21087	\$24.03
NY	597	A2638371	02-01	M5	REPLACED BOLT HANDLE SPRING & RIVET BOLT SPRING & ACTION SPRING, SAFETY &	21036	\$22.43