

NY	597	A2646176	04-01	M142	ADJUSTED MAGAZINE, REPLACED EJECTOR, SAFETY & FUNCTION CHECKED AND	21177	\$20.00
TX	597	A2647351	04-01	DOES NOT EJECT/EXTRACT.	CHECKED EXTRACTOR, BBL, CHAMBER, TRIGGER ASSY, BOLT ASSY, MAGAZINE,	21087	\$38.52
AL	597	A2646157	04-01	M10	HONED CHAMBER.	21056	\$22.50
OH	597	A2647305	04-01	HALL EJECTOR & CLIP FELL APART.	INSTALLED BOLT ASSY & NEW TYPE EJECTOR, CLEANED, CHECKED AND TEST	21060	\$81.09
FL	597	A2648224	04-01	M10	INSTALLED MISSING EXT, SPRING & PLUNGER AND TEST FIRED.	20624	\$41.30
OK	597	A2647565	04-01	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.95
OR	597	A2648730	04-01	MISFIRES, JAMS.	INSTALLED NEW STYLE EJECTOR, TESTED AND CLEANED.	20023	\$40.55
OR	597	A2648770	04-01	JAMS.	INSTALLED NEW UPDATED EJECTOR AND TESTED.	20023	\$37.93
CT	597	A2648661	04-01	M23, M33	RELIEVED PORT FOR MAG & LATCH, CHECKED OVER, CLEANED & OILED, SAFETY	20629	\$47.44
MN	597	A2648669	04-01	M5	REPAIRED BOLT RETAINER TO HOLD BOLT HANDLE IN PLACE, INSTALLED NEW BOLT	20017	\$46.72
MI	597	A2645971	04-01	JAMS.	REPLACED BOLT ASSY & EJECTOR	21030	\$65.84
NY	597	A2648355	04-01	M114	REPLACED EJECTOR, SAFETY & FUNCTION CHECKED AND TESTED.	21177	\$20.00
CAN	597	A2648265	04-01	DOES NOT FEED SHELLS FROM MAG.	REPLACED MAGAZINE, TESTED.	21046	\$20.50
NY	597	A2647172	04-01	M129	REPLACED MISSING EXTRACTOR, PLUNGER & SPRING AND EJECTOR, SAFETY & FUNCTION	21177	\$20.00
IA	597	A2645603	04-01	M9	TOP OF RECEIVER HAD A ROUGH SPOT.	20308	\$33.50
MN	597	A2649817	05-01	M9	ADJUSTED EJECTOR TO ENGAGE SHELLS DEEPER, FREED UP STICKY LINKAGE IN	20017	\$48.01
MN	597	A2649862	05-01	M9	ADJUSTED EJECTOR TO ENGAGE SHELLS DEEPER, SMOOTHED BOLT TRAVEL AND	20017	\$47.01
AL	597	A2651000	05-01	M9	ADJUSTED EJECTOR.	21056	\$22.50
OK	597	A2650793	05-01	M1, M9	ADJUSTED SIGHTS TO ALIGN WITH BORE, BORESIGHTED, INSTALLED NEW STYLE	21047	\$29.58