

IL	597	A2653184	06-01	M33	REPLACED MAG BOX, TEST FIRED.	21028	\$32.98
OK	597	A2657297	06-01	M9	REPLACED RIVET & SPRING, INSTALLED NEW STYLE EJECTOR, SAFETY & TEST	21047	\$31.32
OK	597	A2655981	06-01	M9	REPLACED TRIGGER HOUSING ASSY, INSTALLED NEW EJECTOR, SAFETY & TEST	21047	\$69.98
WI	597	A2653326	06-01	DOESN'T ALWAYS CHAMBER ROUNDS.	TEST FIRED WITH NO PROBLEMS, SENT TO MANN & SON SPTG. GDS.	20616	\$19.01
OR	597	A2653339	06-01	MISFIRES.	UPDATED EJECTOR, REPLACED ACTION SPRING, TESTED AND CLEANED.	20023	\$48.80
AL	597	A2659894	07-01	M9	ADJUSTED EJECTOR.	21056	\$22.50
NY	597	A2657736	07-01	M110	ADJUSTED TRIGGER LINKAGE RIVET, REPLACED EJECTOR, SAFETY & FUNCTION	21177	\$20.00
AK	597	A2658877	07-01	DOES NOT FIRE ALL THE TIME	CLEANED AND TEST FIRED.	21147	\$10.00
NY	597	A2657869	07-01	M201	CLEANED BOLT FACE, SAFETY & FUNCTION CHECKED AND TESTED.	21177	\$20.00
AL	597	A2657869	07-01	M10	HONED CHAMBER.	21056	\$22.00
AL	597	A2657499	07-01	M10	HONED CHAMBER.	21056	\$22.50
OK	597	A2658684	07-01	M9, M15, M23	INSTALLED NEW STYLE EJECTOR & METAL MAGAZINE, SAFETY & TEST FIRED.	21047	\$43.37
OK	597	A2659808	07-01	M23	INSTALLED NEW STYLE EJECTOR, ADJUSTED MAGAZINE ASSY, SAFETY & TEST	21047	\$29.58
OK	597	A2658365	07-01	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.58
OK	597	A2659884	07-01	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$34.58
OK	597	A2659332	07-01	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.58
OH	597	A2657923	07-01	MISFIRES.	INSTALLED NEW TYPE EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$43.98
OH	597	A2659582	07-01	REPAIR.	INSTALLED NEW TYPE EJECTOR, REPLACED BOLT HANDLE & BOLT ASSY, CLEANED,	21060	\$92.57
NY	597	A2659115	07-01	M138	REPLACED EJECTOR, SAFETY & FUNCTION CHECKED AND TESTED.	21177	\$20.00

Subject to Protective Order - Williams v. Remington

BARBER - REM DOCSB0010265

MAE00010181