

Subject to Protective Order - Williams v. Remington

OK	597	A2659488	07-01	M9	REPLACED EJECTOR, SAFETY & TEST FIRED.	21047	\$29.95
OK	597	A2659684	07-01	M9, M10	REPLACED EXTRACTOR, INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$31.55
AL	597	A2657920	07-01	M10, M23	REPLACED MAGAZINE CLIP, HONED CHAMBER.	21056	\$22.50
IL	597	A2654237	07-01		REPLACED RECEIVER AND TEST FIRED.	21028	\$54.09
NY	597	A2657523	07-01	M142	REPLACED TRIGGER HOUSING ASSY, SAFETY & FUNCTION CHECKED AND TEST	21177	\$20.00
MS	597	A2658167	07-01	WAREHOUSE INSPECTION.	WAREHOUSE INSPECTION.	107773	\$15.00
MI	597	A2662264	08-01	GUN WILL ONLY GROUP FROM 1 1/2" TO 2" AT 25 YDS	CLEANED, RECROWNED, TESTED, RETURNED TO FACTORY.	21030	\$38.80
GA	597	A2661213	08-01	JAMS, TWISTS SHELLS.	COULD NOT VERIFY COMPLAINT, TEST FIRED WITH NO PROBLEMS.	20300	\$45.00
KY	597	A2660395	08-01	M23	CUSTOMER STATES STILL JAMS AFTER I INSTALLED NEW EJECTOR & MAG. TEST	21072	\$18.00
NY	597	A2661404	08-01		FIT NEW EJECTOR, FUNCTION TESTED	20312	\$32.79
OH	597	A2662706	08-01	ACTION STICKS, HOLE IN CAST ABOVE WHERE CLIP GOES ON GUN.	GROUND EJECTOR & GROVE IN BOLT CLEANED, CHECKED AND TEST FIRED	21060	\$40.75
OH	597	A2662782	08-01	JAMS.	GROUND EJECTOR SIDE, CLEANED CHECKED AND TEST FIRED.	21060	\$42.25
OH	597	A2662779	08-01	REPAIR.	GROUND SIDE OF EJECTOR FOR BOLT CLEARANCE, ADJUSTED RECOIL SPRING	21060	\$45.75
OH	597	A2662781	08-01	REPAIR.	GROUND SIT OF EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$40.75
OK	597	A2661003	08-01	M9	INSTALLED NEW STYLE EJECTOR, ADJUSTED MAGAZINE, SAFETY & TEST	21047	\$29.58
KY	597	A2660395	08-01	M9, M23	INSTALLED NEW STYLE EJECTOR, REPLACED MAGAZINE AND TEST FIRED.	21072	\$22.23
NY	597	A2661115	08-01	M110	LOOSENEED TRIGGER LINKAGE RIVET, ADJUSTED ACTION TIGHTNESS, REPLACED	21177	\$20.00
CT	597	A2663080	08-01	M9, M10, M23	POLISHED CHAMBER, CHECKED OVER, CLEANED & OILED, SAFETY & FUNCTION	20629	\$40.75
NY	597	A2662061	08-01	M145	REPLACED BOLT SPRING & BOLT SPRING RIVET, SAFETY & FUNCTION CHECKED AND	21177	\$20.00