

Subject to Protective Order - Williams v. Remington

OH	597	A2661438	08-01	CLIP MISSING.	REPLACED CLIP, BOLT ASSY & EJECTOR. REPLACED EJECTOR AND MAG AND TEST FIRED.	21060	\$98.30
CA	597	A2662385	08-01	M9, M23	REPLACED EJECTOR, POLISHED CHAMBER, CHECKED OVER, CLEANED & OILED, SAFETY	20106	\$38.85
CT	597	A2661142	08-01	M23	REPLACED EJECTOR, SAFETY & FUNCTION CHECKED AND TESTED.	20629	\$42.98
NY	597	A2660302	08-01	M137	REPLACED EJECTOR, SAFETY & FUNCTION CHECKED AND TESTED.	21177	\$20.00
NY	597	A2661298	08-01	M137	REPLACED MOD. EJECTOR, CHECKED OVER, CLEANED & OILED, SAFETY & FUNCTION	21177	\$20.00
CT	597	A2662020	08-01	M25	WHSE INSPECTION	20629	\$42.98
MS	597	2963682M	08-01	WHSE INSPECTION.	WHSE INSPECTION	107773	\$15.00
MS	597	2963428M	08-01	WHSE INSPECTION.	WHSE INSPECTION.	107773	\$15.00
NY	597	A2665590	09-01	M137	ADJUSTED ACTION TIGHTNESS, SAFETY & FUNCTION CHECKED AND TESTED.	21177	\$20.00
OK	597	A2665235	09-01	M9	ADJUSTED EJECTOR & MAGAZINE, SAFETY & TEST FIRED.	21047	\$32.23
NE	597	A2664419	09-01	MAG FALLS OUT.	ADJUSTED MAG LATCH, SHARPENED MAG SLOT AND TEST FIRED.	21106	\$27.40
OR	597	2963625M	09-01	M5	ADJUSTED OPERATING HANDLE RETAINING SPRING.	20200	\$10.00
NY	597	A2664580	09-01	M34	CLEANED SAFETY, FUNCTION CHECKED AND TESTED.	21177	\$20.00
OH	597	A2666373	09-01	SHELL JAMS IN BBL WHEN SHOT.	GROUND EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$47.75
AL	597	A2664655	09-01	M10	HONED CHAMBER.	21056	\$22.50
AL	597	A2663876	09-01	M23	HONED CHAMBER.	21056	\$22.50
OK	597	A2665075	09-01	M9, M23	INSTALLED NEW STYLE EJECTOR, REPLACED TRIGGER HOUSING, SAFETY & POLISHED CHAMBER, REPLACED MAGAZINE CLIP.	21047	\$71.19
AL	597	A2663004	09-01	M23		21056	\$31.28
AL	597	A2665863	09-01	M10	POLISHED CHAMBER.	21056	\$22.50