

OK	597	A2666220	09-01	M23	REPLACED ACTION SPRING & RECEIVER PLUG, SAFETY & TEST FIRED.	21047	\$29.46
AL	597	A2666953	09-01	M23	REPLACED MAGAZINE CLIP.	21056	\$31.25
OR	597	A2664634	09-01	SHOOTS TO RIGHT, SIGHTS ARE OFF.	RESET SIGHTS, BORESIGHTED.	20023	\$26.50
NY	597	A2664038	09-01	M993	SAFETY & FUNCTION CHECKED AND TESTED. NO FAULT FOUND.	21177	\$20.00
AL	597	A2668791	10-01	M5, M9	ADJUSTED BOLT HANDLE SPRING & EJECTOR.	21056	\$22.50
CT	597	A2667214	10-01	M25	CHECKED OVER, CLEANED & OILED, SAFETY & FUNCTION TESTED.	20629	\$40.75
OH	597	A2668510	10-01	OPERATING HANDLE PULLS OFF GUN, SITTING IN BOX.	GROUND EJECTOR FOR BOLT CLEARANCE, REPLACED BOLT ASSY & BOLT HANDLE.	21060	\$94.84
OH	597	A2668880	10-01	REPAIR.	GROUND SIDE OF EJECTOR TO CLEAR BOLT, CLEANED, CHECKED AND TEST FIRED.	21060	\$42.25
OH	597	A2668797	10-01	NOT FIRING, GUN JAMS AFTER BEING LOADED.	GROUND SIDE OF NEW TYPE EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$41.75
AL	597	A2667691	10-01	M10	HONED CHAMBER, CHECKED SAFETY	21056	\$22.50
AL	597	A2666708	10-01	M10	HONED CHAMBER.	21056	\$22.50
AL	597	A2668917	10-01	M10	HONED CHAMBER.	21056	\$22.50
AL	597	A2667274	10-01	M10	HONED CHAMBER.	21056	\$22.50
AL	597	A2667145	10-01	M10	HONED CHAMBER.	21056	\$22.50
OK	597	A2668867	10-01		OPERATING HANDLE IS OK, ADJUSTED MAGAZINE, SAFETY & TEST FIRED.	21047	\$27.35
AL	597	A2666989	10-01	M10	POLISHED CHAMBER.	21056	\$22.50
OH	597	A2668510	10-01	OPERATING HANDLE COMES OFF, SECOND TIME IN FOR SAME REPAIR.	REPLACED BOLT ASSY & BOLT HANDLE, CLEANED, CHECKED AND TEST FIRED.	21060	\$84.84
OH	597	A2667463	10-01	RECEIVER COCKED OPEN AND WILL NOT RELEASE.	REPLACED BOLT ASSY & BOLT HANDLE, GROUND NEW STYLE EJECTOR, CLEANED,	21060	\$83.84
OH	597	A2663186	10-01	BOLT PULL HAS FALLEN OFF, WON'T STAY ON.	REPLACED BOLT ASSY, CLEANED, CHECKED AND TEST FIRED.	21060	\$85.36