

OK	597	A2667408	10-01	M23	REPLACED BOLT SPRING & RIVET, SAFETY & TEST FIRED.	21047	\$30.42
OH	597	A2667227	10-01	PARTS MISSING.	REPLACED STOCK, CLEANED, CHECKED AND TEST FIRED.	21060	\$92.74
TX	597	A2668439	10-01	DOES NOT FEED PROPERLY.	TEST FIRED, SUSPECT AMMO PROBLEM.	21017	\$21.50
OK	597	A2670808	11-01	M9, M10	REPLACED BOLT RIVET & SPRING, INSTALLED NEW STYLE EJECTOR, SAFETY &	21047	\$33.77
MS	597	99999		WHSE INSPECTION.	WHSE INSPECTION.	107773	\$15.00
LA	597	294372M	-	M10	INSTALLED LONGER EXTRACTOR.	21025	\$24.09
OK	597	A2520507	-		INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$34.46
MN	597	AZ641643	-	M9, M23	POLISHED CHAMBER, ADJUSTED EJECTOR, SMOOTHED BOTTOM OF BOLT AND TEST REASSEMBLED MAG LATCH. REPLACED.	20017	\$47.90
NY	597	7774992	-	M142	EJECTOR, SAFETY & FUNCTION CHECKED.	21177	\$20.00
NY	597	27772868	-	M145	REPLACED BOLT SPRING & RIVET, BOLT HANDLE AND EJECTOR, SAFETY & FUNCTION	21177	\$20.00
NY	597	296257M	-	M145	REPLACED BOLT SPRING & RIVET, SAFETY & FUNCTION CHECKED AND TESTED.	21177	\$20.00
OK	597	0946424M	-		REPLACED BOLT SPRING RIVET & BOLT HANDLE SPRING, SAFETY & TEST FIRED.	21047	\$33.97
CAN	597	999999.	-	CROSS THREADED.	REPLACED CLAMP SCREW.	268418	\$0.79
MI	597	2747049	-	M23	REPLACED EJECTOR AND TEST FIRED.	20108	\$21.15
IL	597	A2683030	2002		REPLACED EJECTOR, MAGAZINE BOX, REMOVED BURRS AT CHAMBER AREA AND	21028	\$40.73
CAN	597	999999	-	M9	REPLACED EJECTOR.	268418	\$6.38
IL	597	2950450	-	M10, M33	REPLACED EXTRACTOR AND MAGAZINE BOX, NEW BOLT HANDLE AND TEST FIRED.	21028	\$48.26
CAN	597	999999	-	M23	REPLACED MAG.	268418	\$17.11
MI	597	29427817	-	WON'T FEED LAST CARTRIDGE.	REPLACED MAGAZINE AND TESTED.	21054	\$25.69

Subject to Protective Order - Williams v. Remington

BARBER - REM DOCSB0010269

MAE00010185