

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
 GENERAL CONDITION: NEW R #: 06681
 OUTSIDE WORK: NO DATE: 3-15-71
 FIRED AMMO TYPE: _____ FROM: KENNETH JOHNSON
 & CONDITION: _____ STURTEVANT, WISC.
 PROOF: R.E.P. B INSP: 73 TEST: 87 GUN #: 6312955
 HEADING: O.K. CODE: L.T. = 2/70
 BREECH OPENING: _____ GA./CAL.: 7MM
 RECOIL SHOULDERS: EXCESSIVE RADIUS AT REAR CHECKED BY: C. PROSSER
 CHAMBER: O.K. BODY. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

COMPLAINT: CLOSES HARD OVER SHELL. FIRED WHILE TRYING TO
CLOSE.

INCIDENT: CLOSE HARD

PLAINTIFF'S
EXHIBIT

3279

COMMENTS: THE EXCESSIVE RADIUS AT REAR OF RECOIL SHOULDER
CAUSES THE BOLT TO CAM HARD WITH A ROUND IN THE
CHAMBER. THERE APPEARS TO BE NOTHING WRONG WITH
THE TRIGGER ASSEMBLY. THE CUSTOMER LIKELY, (NADVERT-
ENTLY TOUCHED THE TRIGGER WHILE TRYING TO FORCE
THE BOLT HANDLE DOWN.