

REPLACED BOLT HANDLE.	21072	\$19.02	6	136566
CLEANED & DEBURRED AS NEEDED.	21125	\$24.00	1	127630
RETURNED TO FACTORY.	20106	\$34.04	20	135549
TEST FIRED, WORKED FINE BUT A LITTLE STIFF	21072	\$21.27	3	141927
INSTALLED BACKERS.	21072	\$20.00	1	139984
SENT TO PADUCAH FOR REPAIRS.	21047	\$36.08	30	132232
REPLACED BOLT STOP.	21072	\$19.02	2	142073
SHIPPED TO PADUCAH SHOOTERS.	20616	\$19.32	22	124210
TOOK TO FACTORY IN MAYFIELD, KY TO BE CHECKED, ALL OK.	21072	\$32.00	4	139931
TOOK TO FACTORY IN MAYFIELD, KY TO BE CHECKED, ALL OK.	21072	\$22.00	4	139932
RETURNED TO FACTORY	20616	\$18.12	12	153656
REPLACED BOLT BODY & HEAD.	21072	\$19.47	7	135983
REPLACED BOLT STOP AND INSTALLED ACTION SHIMS.	21072	\$22.00	4	139955
REPLACED BOLT STOP	21072	\$18.58	1	142245