

REPLACED BOLT STOP.	21072	\$19.02	3	141930
REPLACED BOLT STOP, CHECKED UPDATE, ALL OK.	21072	\$21.04	1	142235
REPLACED BOLT BODY, INSTALLED LEFT BACKER & RIGHT BACKER.	21072	\$19.00	1	136327
REPLACED TRIGGER ASSY AND BOLT STOP.	21072	\$19.02	4	135630
RETURNED TO PADUCAH FOR REPAIRS.	21047	\$30.07	1	132250
LUBED FIRING PIN ASSY & BOLT HEAD.	21072	\$19.02	2	142057
REPLACED BOLT BODY.	21072	\$19.02	7	136588
REPLACED BOLT BODY.	21072	\$19.02	7	136492
REPLACED BOLT BODY.	21072	\$19.02	5	136515
REPLACED BOLT BODY.	21072	\$18.58	5	136513
REPLACED BOLT BODY.	21072	\$18.58	5	136512
REPLACED BOLT BODY.	21072	\$19.02	8	136538
REPLACED BOLT BODY.	21072	\$19.02	3	136578
REPLACED BOLT BODY.	21072	\$19.47	5	135945
REPLACED BOLT BODY.	21072	\$19.47	7	136575
REPLACED BOLT BODY.	21072	\$19.47	7	136574
REPLACED BOLT BODY.	21072	\$19.02	5	136524
HAD TO UNLOCK BOLT SO IT WOULD CLOSE, TESTED SAFETY.	21072	\$24.00	1	139947
REPLACED BOLT STOP AND INSTALLED BACKERS.	21072	\$20.00	1	139976