

SENT TO PADUCAH SHOOTERS SUPPLY.	20106	\$21.94	15	135557
REPLACED BOLT HANDLE.	21072	\$21.04	1	142053
REPLACED BROKEN FIRING PIN ASSY.	21072	\$19.02	3	141925
REPLACED BOLT HANDLE.	21072	\$19.04	1	142280
REPLACED BOLT HANDLE.	21072	\$19.47	2	142075
REPLACED BOLT HANDLE.	21072	\$21.04	7	141903
REPLACED BOLT BODY, INSTALLED BACKERS.	21072	\$19.00	1	139979
REPLACED BOLT STOP & BOLT BODY, INSTALLED BACKERS.	21072	\$20.00	2	139992
REPLACED BOLT BODY, INSTALLED ACTION BACKERS.	21072	\$20.00	1	130095
REPLACED BOLT BODY, INSTALLED LEFT BACKER & RIGHT BACKER.	21072	\$18.58	6	136303
REPLACED BOLT BODY, INSTALLED LEFT & RIGHT BACKERS.	21072	\$19.00	1	136344
REPLACED BOLT BODY.	21072	\$18.00	1	139998
SENT CUSTOMER BOLT HANDLE.	21072	\$17.45	1	141913
ADJUSTED & ASSEMBLED BOLT, CLEANED & OILED, FUNCTION & SAFETY TESTED.	20628	\$41.25	6	136851
REPLACED BOLT HEAD, TESTED	21072	\$19.02	2	142084
ADJUSTED CROOKED SCOPE, HAS BEEN UPDATED ALL OK.	21072	\$19.02	1	142206
RETURNED TO PADUCAH	20023	\$23.72	1	137762
REPLACED MAG LATCH.	21072	\$20.09	1	142054
REPALCED STOCK, CHECKED UPDATE.	21072	\$21.99	1	142100
REPLACED STOCK, BOLT BODY, LEFT & RIGHT BACKERS.	21072	\$20.09	1	136339