

Paducah Shooters Supply/ Model 710 Report
07-08-01

Date	Guns In-House	Reason for Repair	Other Comments
4/19/2001	26	Update - All	needs 25 more bolt bodies
4/24/2001	35	Update - All	1 gun with possible off-set scope rail holes in r/cvr
4/27/2001	85	Update - All More came in that have not been counted	needs about 100 bolt bodies
5/4/2001	125	Most update - had not looked at all of them yet	shipped out about 100 week of 3/30-01
5/7/2001	85	Most Update - few from consumers	1 gun in second time; harder to cam bolt handle down than before update - Adam @ Paducah could find no fault, thinks consumer operated bolt with ISS engaged- Paducah had been shipping guns back with ISS in the "safe" position - will start shipping as of now in the "fire" position

Subject to Protective Order - Williams v. Remington

BARBER - REM DOCSB0010440

MAE000010356