

the bolt at anytime with the safety on safe. To view more details regarding this modification, go to:

[http://www.remington.com/Safety\\_Modification\\_Program/remington\\_safety.htm](http://www.remington.com/Safety_Modification_Program/remington_safety.htm)

Auto-Response 11/02/2005 01:11 PM

Title: How can I adjust the trigger pull on my Model 700?

Link: [http://remington.custhelp.com/cgi-bin/remington.cfg/php/enduser/popup\\_adp.php?p\\_faaid=41-&p\\_created=954461361](http://remington.custhelp.com/cgi-bin/remington.cfg/php/enduser/popup_adp.php?p_faaid=41-&p_created=954461361)

Title: Why won't Remington sell me a bolt assembly for my Model 700 so I can just install it myself?

Why do I have to return it to the factory?

Link: [http://remington.custhelp.com/cgi-bin/remington.cfg/php/enduser/popup\\_adp.php?p\\_faaid=333-&p\\_created=1085085064](http://remington.custhelp.com/cgi-bin/remington.cfg/php/enduser/popup_adp.php?p_faaid=333-&p_created=1085085064)

Title: What is the difference between the Model 700 action & the Model 40-X action?

Link: [http://remington.custhelp.com/cgi-bin/remington.cfg/php/enduser/popup\\_adp.php?p\\_faaid=184-&p\\_created=1000825447](http://remington.custhelp.com/cgi-bin/remington.cfg/php/enduser/popup_adp.php?p_faaid=184-&p_created=1000825447)

Title: What is the difference between the Model 700 ADL and the BDL?

Link: [http://remington.custhelp.com/cgi-bin/remington.cfg/php/enduser/popup\\_adp.php?p\\_faaid=67-&p\\_created=954436755](http://remington.custhelp.com/cgi-bin/remington.cfg/php/enduser/popup_adp.php?p_faaid=67-&p_created=954436755)

Title: When I order a new bolt assembly for my Model 700 Muzzleloader, what parts will

Link: [http://remington.custhelp.com/cgi-bin/remington.cfg/php/enduser/popup\\_adp.php?p\\_faaid=239-&p\\_created=1003246966](http://remington.custhelp.com/cgi-bin/remington.cfg/php/enduser/popup_adp.php?p_faaid=239-&p_created=1003246966)

Customer (Tom Ward) 11/02/2005 01:11 PM

I have a Remington 700, .270 caliber rifle, serial number 86287639. I believe it was manufactured before 1982 and is eligible for recall and repairs to the firing/safety mechanism. Reportedly, the series of small, metal parts that control the gun's firing mechanism were prone to failure, making the rifle accidentally discharge without the trigger being pulled (i.e. The safety must be moved to off in order to open the bolt and unload the rifle causing the rifle to fire without the trigger being pulled). Please advise.

Thank you,

Tom Ward  
11110 Chaucer St. SE  
Olympia, WA 98501  
360-705-8726