

Customer Complaint

MODEL: 700 PCL
R # : 20000
DATE: 12-10-90
FROM: FLYNN, J. D.
FIRING ARM TYPE: 1000
GUN # : 6884951
CODE: CTR 440
GAT/CAL.: 25-01
CHECKED BY: C. F. R. 10
APPROVED: _____
APPROVED: _____
APPROVED: _____
APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style)

GENERAL CONDITION: EXCELLENT
SLIDE BAR: W/O
FIRING ARM TYPE: _____
CONDITION: _____
PRICE: \$100.00 INSP.: _____ TEST: _____
READING: 0.00
BREECH OPENING: _____
RECOIL SHOULDERS: _____
CHAMBER: 0.00
TEST: NO

COMPLAINT: "BULLET STICKS IN CHAMBER ALSO BOLT IS
IMMOVABLE FOR SOME REASON."

INCIDENT: _____

PLAINTIFF'S
EXHIBIT

3286

COMMENTS: THE CUSTOMER PULLED THE BULLET OUT OF THE
CASE LEAVING IT IN THE THROAT. THIS APPARENTLY
IS AN AMMUNITION PROBLEM (PER M. WALKER).
THE BOLT CATCHING IS CAUSED BY PUSHING THE
SAFETY ON BEFORE LOCKING THE BOLT THUS CATCH-
ING THE SAFETY PIN IN THE LOCKING CAM.