

Customer Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BCL
 GENERAL CONDITION: GOOD R #: 29327
 OUTSIDE WORK: EXTRACTOR PISTON - BRASS - SEE DATE: 12-15-70
TELESCOPE ADJUSTED - ENGAGEMENT - SCREEN FROM: HARPER ST. 300
APPEARS UNTOUCHED. WILLIAMSPOOT, PA.
 FIRED AMMO TYPE: _____ GUN #: 6262972
 & CONDITION: _____ CODE: W5-9/10
 PROOF: R.E.P.E INSP.: 47 TEST: 55 SA./OAL: _____
 HEADLINE: _____ CHECKED BY: C. PRINCE
 BREACH OPENING: _____ APPROVED: _____
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: No APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____
NO DEFECTIVE OR BROKEN COMPONENTS.

COMPLAINT: "FIRED UPON CLOSING"

INCIDENT: FOLLOWED DOWN

COMMENTS: SEAR-CONNECTOR ENGAGEMENT .003, MINIMUM IS .015,
THIS LETS THE SEAR SLIP OFF THE CONNECTOR UNDER
PRESSURE AND FOLLOW DOWN RESULTS.

PLAINTIFF'S
EXHIBIT

3296

AL 0029828

1 of 1