

Model 700 Repair Codes Combined RARC & Factory Results 11/1/2004 - 11/30/2004			
		Date Produced	Date Repaired
Repair Code	Description	Produced	Repaired
M127	Trigger pull out of factory Specs	20	204
M125	stock cracked	18	174
M129	Fails to extract	14	181
M153	Receiver plug screws broken	13	74
See table below for serial numbers			