

4039	NO FAULT FOUND	SC	FARLEY	KEITH
4006	TRIGGER HAS BEEN ALTERED	CA	KASPER	GORDON
4039	NO FAULT FOUND	NY	KELLY	OWEN
4040	PIECE OF PAPER STUCK BEHIND SEAR SAFETY CAM	TX	VAN FLEET	THOMAS
4006	ADJUSTED OUTSIDE FACTORY	MN	HANLON	THOMAS
4006	ALTERED/ADJUSTED COMPONENTS	PA	JOE RIGGS SPORTING GOODS	
4040	REF: 60 MIN. PROGRAM	OK	MASSAD	GEORGE
4006	ALTERED PARTS	RI	ARQUEBUS CO	
4006	TRIG. STOP SCREW HAD BEEN RE-SET	OK	COOPER	THOMAS
4040	UNSPECIFIED	ME	ELLIS	JOHN
4039	NO FAULT FOUND	PA	MARTIN	TODD
4006	ADJUSTED/POORLY MAINTAINED	PA	MACINOWSKI	RICHARD
4040	REF: 60 MIN. PROGRAM	WV	ROSS	ROGER
4015	POORLY MAINTAINED	VT	HALNON	LEONARD
4039	NO FAULT FOUND	MS	ARRINGTON	A.P.
4015	POORLY MAINTAINED	AL	PAYNE	CLAYTON
4006	ADJUSTED OUTSIDE OF FACTORY	SC	SOUTHLAND GUN WORKS, INC.	
4039	NO FAULT FOUND	MD	OLDS	D. R.
4006	ADJUSTED OUTSIDE OF FACTORY	NC	SPANGLER	JAMES
4039	UNABLE TO DUPLICATE CUSTOMER'S CONCERN	TX	COLLINS	HERB
4006	ALTERED OUTSIDE OF FACTORY	NY	BUTTON	DENNIS
4039	NO FAULT FOUND	VA	KRIDLER	BRADLEY