

4039	NO FAULT FOUND	MI	THOMASIAN	JACK
4006	ALTERED PARTS	PA	AUSTIN	CHARLES
4006	ALTERED COMPONENTS	PA	RELICK	RON
4006	ALTERED	PA	KITSCH	KENNETH
4006	ALTERED PARTS	TX	BROWN	RAY
4006	ALTERED OUTSIDE FACTORY	AZ	HANSING	JAMES
4006	RE-SET OUTSIDE OF FACTORY	PA	KAEFER	CHARLES
4040	TRIGGER PULL BELOW FACTORY SPECS.	MI	RYBAK	TERENCE
4015	POORLY MAINTAINED	WI	ROOT	E.A.
4006	TRIGGER ADJ. SCREWS HAD BEEN RESET	KY	STEVENS WHOLESALE, INC.	
4006	ADJUSTED OUTSIDE FACTORY	KY	STEVENS WHOLESALE, INC.	
4039	NO FAULT FOUND	PA	WILDERNESS CONNECTION	
4006	ALTERED/ADJUSTED PARTS	NM	MCCARTY	DARWIN
4040	REF: 60 MIN. PROGRAM	MT	KETO	GEORGE
4006	TRIG. HAD BEEN ADJUSTED OUTSIDE FACTORY	OR	SHAFFER	ARTHUR
4039	NO FAULT FOUND	PA	MISHKO	PETE
4015	POORLY MAINTAINED	VA	JACKSON	EUGENE
4006	ADJUSTED OUTSIDE OF FACTORY	NM	WILSON	JAMES
4040	UNEXAMINED	MO	EIBERT	GARY
4006	ALTERED OUTSIDE FACTORY	NY	HANLON	JAMES
4039	NO FAULT FOUND	PA	FARMU	ROBERT
4006	SEAR ENGAGEMENT SCREW HAD BEEN RESET	TX	JACKSON	DON