

Phillip Reesor

---

From: Lance, Kevin D.  
Sent: 07/26/2004 10:49:25 AM  
To: Reesor, Phillip K.  
CC:  
BCC:  
Subject: RE: 710-270 Chamber Images

Phillip,

Do you have any idea what caused this?

Kevin

---

From: Reesor, Phillip K.  
Sent: Monday, July 26, 2004 9:11 AM  
To: Diaz, Danny; Franz, Scott  
Cc: Lance, Kevin D.; Keeney, Mike; Thweatt, Ed T.  
Subject: 710-270 Chamber Images

<< File: 71163349 270 Chamber 1.tif >> << File: 71163349 270 Chamber 2.tif >> << File: 71163349 270 Chamber 3.tif >>

Gentlemen, the above borescope images are of one of the 710 extruded receiver rifle chambers. Basically, we were performing the Jack Function Test on the 270 rifles and this one was very hard to open after firing each shot. Upon inspection with a borescope the above very nasty gooves were found in the chamber. This gun has been pulled from any additional livefire testing and will only be used as a Drop Test sample.

Phillip Reesor

Subject to Protective Order - Williams v. Remington

BARBER - 5.30.060001168

ETE00000583