

Model 700 Repair Codes Combined RARC & Factory Results 1/1/2004 - 11/30/2004			
Date Date			
Repair Code	Description	Produced	Repaired
M127	Trigger pull out of factory Specs	20	204
M125	stock cracked	18	174
M129	Fails to extract	14	181
M153	Receiver plug screws broken	13	74
See table below for serial numbers of RAAs affected			