

P NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
GENERAL CONDITION: NEW R #: 22730
OUTSIDE WORK: NO DATE: 10-16-70
FIRED AMMO TYPE: _____ FROM: LIVONIA,
& CONDITION: _____ MICH.
PROOF: -R.E.P. INSP.: _____ TEST: _____ GUN #: 6278113
HEADING: _____ CODE: _____
BREACH OPENING: _____ GR./CAL.: 3006
RECOIL SHOULDERS: _____ CHECKED BY: C. PROSSER
CHAMBER: _____ APPROVED: _____
TEST: FUNCTION ONLY APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

CONNECTOR IS .005 UNDERSIZE ON 1.080
CLEARANCE) 1.083 DIMENSION (TRIGGER

COMPLAINT: FOLLOWS DOWN

INCIDENT: _____

COMMENTS: CONNECTOR BEING TIGHT ON TRIGGER DID NOT RETRACT,
ACTION WOULD NOT COCK. AS LONG AS THE CONNECTOR
STAYED IN POSITION ON THE TRIGGER THE RIFLE WOULD
WORK O.K.



AL 0029843