#### Model 700 XCR -Coatings-G.Sietsema

- Marketing has approved color on trigger guard and components
- Need an update on testing (salt fog, abrasion, endurance) that was to be complete on 9/2/04.
- Need an update on DAT/T&P to establish material flow process with vendor.
- Need an update on competitive samples to independent test lab that we agreed to go ahead and get started per the last meeting.
- Writers Seminar is in 4 weeks!

### Model 700 New Varmint Line - Mroz/Balio

· Status Update on production

## Model XR-100-Mroz

- Status Update on Gun DAT, T&P, etc.
- Status Update on Owners Manual Has copy been signed off on by Dale Wills?
- Confirm that stocks have been ordered with Boyd's Wadas/Balio

### Model 700 SPL Fire Control - Perniciaro/Diaz

Update on testing/timing. – Perniciaro

### Fluted Firing Pin - Perniciaro

- Status
- Production Ramp up Ilion

# Fluted Firing Pin - Perniciaro

- Status
- Production Ramp up Ilion

## 6.8mm Rem SPC Bolt Head/Extractor Development - Perniciaro/Diaz

- Status of M700P LTR
- Timing/Cost of Development
- Model Selection/Strategy Keep it Lean

### Ilion Quality Issues - Rifles

### Model 7400 Cracked Fore Ends - S. Perniciaro/Balio

- Ilion to advise of status of replacement fore ends for Rivolier.
- Trull/Perniciaro to update team on recent visit.

### Model 700 Varmint Accuracy Standards -S. Perniciaro

- We need to establish a protocol to insure that our varmint rifles meet a level of accuracy that is congruent with the consumers perception that a varmint rifle should be capable of delivering MOA accuracy out of the box.
- We already charge more for these guns, but we can likely get an additional premium
  if we can guarantee a level of performance.
- We need to firm up our future business of high revenue, high margin products and
  give the consumer "insurance" in the form of a guarantee that they are justified in
  paying the premium for a varmint rifle vs. a price point rifle.

## 7400 SGS-New gas system – S. Perniciaro

- Pernciaro to update on status.
- Team to decide if we should push forward.

C:\Program Files\\CDI\CrackerLoaderREM\REMEmail\rawblob\20060107071736A00006176.docPage 4

6/12/2006