

>Rust on trigger components;
>Trigger block coating flaked off;
>Floor plate pivot pin loose into the trigger guard holes.
>Pictures showing defects listed above are enclosed.
>Through this message I simply intend to let you know about the poor quality
>of the so called "tack drivers" released from your Custom Shop, despite
>their price ranges in Italy from \$3,000 to \$4,000.
>It is very realistic that my friends and I will not buy Remington again.
>Regards.
>
>Luca Belli
>Via Nuvolari 3
>46036 Revere
>Italy
>
>

Dear Gaston,

this is a copy of the e-mail I received from Mr Luca Belli, together with
the pictures.

However I would like to point out that the gun shop sell this rifle at
Euros 2.600 + 20% VAT tax.

Best regards,

Lello

Paganini sas - Torino (Italy)
www.paganini.it

This email has been scanned for viruses by McAfee Webschild e500 virus scanner.