

Sights: The front sight including screws has 4 pieces; base, front sight, and 2 screws. The front sight is dovetailed in. This must be lapped out to the side to remove. Sometimes it will have a 5th piece, which is the hood. The back sight has 5 pieces: base, slide, and aperture, & 2 screws (windage and elevation). We do not sell stainless steel sights. On the parts list if says bright, this means unfinished. The sight would have to be brased on and then finished (the brazing process can hurt the finish on the sight.).

Model 700 misc.

We do not sell barrels, complete bolts, or actions. This is factory only!

New Model 700 with the ISS system. When the bolt is locked in engagement do not use the ISS system. This will cause the firing pin to bind and jam. Will have to be sent in to the factory for repair.

You cannot interchange centerfire calibers!

Every single bbl action is tested for accuracy at the factory.

Every receiver is cut from a single block of steel. We are the only manufacturer that does this.

You cannot change from the new style ISS system on a firearm to one that does not have it. The sear engagement is not the same and this would be dangerous.