Thank you for contacting Remington Country. **Your Model 12 was produced** around 1911. To view the history on this model, go to:

http://www.remington.com/aboutus/gunhistory.htm

Due to the many variables involved with valuation, we would encourage you to refer to the many publications that are available on the subject of gun values or have it appraised by a collector. Many of these books are available through public libraries or local bookstores. For your convenience we have provided a listing of the more popular books:

Note: Remington does not accept responsibility for the goods or services provided by these sources.

Blue Book of Gun Values Blue Book Publications 8009 34th Avenue South #175 Minneapolis, MN 55425 800-877-GUNS bluebookinc.com

Flayderman's Guide to Firearm Values
Gun List
Modern Gun Values
Krause Publications
700 East State Street
Iola, WI 54990-0001
847-573-8530

Gun Trader's Guide Shooter's Guide Stoeger Publishing Company Mansard Court Wayne, NJ 07470

1100 not cycling

Thank you for your inquiry. The Model 1100 is designed to shoot either 2 3/4" or 3" shells, not both. The magnum barrel has a smaller gas orifice hole and 2 3/4" shells will not produce enough pressure to cycle in the magnum barrel.

Autoloader not cycling

We apologize for any inconvenience you may be experiencing. Check to make sure that the gas orifice hole is clear and clean. Also, the magazine tube should not be lubricated. The action spring that pushes the bolt forward may need cleaning and lubricating. The stock will need to be removed for this inspection.