

http://www.remington.com/Safety_Modification_Program/remington_safety.htm

Model 660

Dear Mr. Humble,

Thank you for contacting Remington Country. Your Model 660 was produced in 1971 and should be inspected for a trigger recall. We suggest taking or sending your firearm to a Remington Authorized Repair Center or our factory for evaluation.

You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state:

<http://www.remington.com/repairsvc/ModelSelection.asp>

To view more information on this safety message, go to:

http://www.remington.com/Safety_Modification_Program/remington_safety.htm

742

We apologize for the inconvenience. Following are some sources for repair of older Remington models. We no longer house any parts for this model. It may be difficult for local gunsmiths to find parts for obsolete models. For your convenience we have included a link below to a list of establishments that may offer parts or services for your older Remington firearm:.

<http://www.remington.com/support/parts/obsolete.htm>

Schumaker Gunsmithing
1807 19th St
Parkersburg, WV 25101
304-485-8771

Mann & Son Sporting Goods
515 W Water St.
Pinckneyville, IL 62274
Phone: 618-357-2911
Fax: 618-357-3658

No special order production gun options/ rifle sights

We do not offer special orders on production rifles. The 700 barrels are drilled on the line and assembled for shipment directly to wholesalers and distributors.