Action: Shumway to update team on progress.

Salt Bleed Out

OBJECTIVE: Quality Improvement

We continue to see bluing salt bleed out all too frequently on both our shotguns and our rifles. Other manufacturers do not appear to have the same degree of problems with this issue.

ACTION: Ilion to advise on progress to eliminate(no-bleed tank project)

ILION BASED RIFLE PRODUCTS

2004 New Rifles

Model 700 CDL (Classic Deluxe)

NPP-2004-24 RAMACS(7007,7015,7011,7017,7047,7049,7051,7053)

OBJECTIVE: New Product

Action: Production Status from Ilion

 Model Seven Synthetic Stock OBJECTIVE: New Product

Action: Status of mold texturing and samples for SHOT to Trull

Model 700 204 Ruger

OBJECTIVE: New Product

NPP-2004-36, 37,38 RAMACS 6196 (LV SF), 7467 (VLS), 7527 (ADL SYN)

ACTION: Test and Production Status from Ilion

2005 Prospective Ilion New Rifle Programs

2005 New Products

OBJECTIVE: New Product,

- Model 700 Syn Stock Redesign Status
- Model 700 Special Purpose Synthetic Trull to issue NPP prior to Meeting.
- Update to Varmint Line Review/discuss new concepts. Review McMillan stock designs
- Model 700 Classic thoughts Any Ideas? 35 Remington?
- Ultimate Fireamis Muzzleloader—Samples received. Need to review and address path forward.

Ilion Engineering Topics -- Rifles

Alternative Metal Finish for Stainless Rifles

OBJECTIVE Product Enhancement

Action: Sietsema to brief team on Bodycote process, what it is, how it performs, and what it costs.

Roller Burnish for Rifle Chambers

OBJECTIVE Product Enhancement

Engineering reported at last meeting that this process is being held up due to chamber eccentricity issues. Bulk of problem appears to rest with current CF heading process at llion.

Action: Engineering to update on status. Can we implement on 7400/7600's?

Ilion Quality Issues - Rifles

C\Program File CD\CrackerLoaderREM\REMEmail\rawblob\20060107001655A00077998.docPage 4 6/12/2008