Bolt-Action Rifle "Lays Left" Issue OBJECTIVE: Quality Issue

Action: Engineering and Quality to Provide a brief overview of implementation of corrective action on issues uncovered by team.

Model 700/Seven Trigger Pull Weights

OBJECTIVE: Quality Issue

Sales and Marketing are receiving a great deal of feed back from customers and consumers that we are losing sales at a devastating level to the Savage Accutingger offerings.

Action: Let's finalize direction and path forward given plans on the table at this meeting.

Centerfire Rifle Chamber Specs – Ilion reamers as compared to SAAMI

OBJECTIVE: Quality Issue

Action: Perniciaro/Diaz to advise if proposals will be made to SAAMI to add freebore to cartridge drawings determined to be an issue from last meeting.

Model 7400 Improvement Project

OBJECTIVE: Quality Issue

ACTION: Need status update from Findlay. Also, need to determine if we can have 150 replacement barrels in 35 Whelen for Borchers by this spring. They have big problems with their guns in Spain right now. Trull needs to be prepared to address performance concerns with key customers at IWA show complete with timelines that manufacturing can support.

Bolt-Action Rifle Torque Settings at Final Assembly

OBJECTIVE: Quality Issue

ACTION: Manufacturing to confirm that processes have been changed at final

assembly.

R&D TOPICS

E-Town Development Topics

Model 597 Performance Improvement
 OBJECTIVE: Performance Improvement of 597
 Action: Diaz to advise of redesign efforts.

Model 7600 223 Rem

OBJECTIVE New Product

Action: Diaz to update on DAT status. Guns were received from Ilion. Advise of

anticipated completion date.

MAYFIELD BASED RIFLE PRODUCTS

2004 New Rifle Product - Mayfield

Model 504

OBJECTIVE: New Product

Action: Golemboski to advise of production status.

C\Program File CD\CrackerLoaderREM\REMEmail\rawblob\20060107071736A00006171.docPage 5 6/12/2008