CODE	MALFUNCTION:INDEX	700 ADL	700 BDL	700 SS	700 Police	700 ML	Model 7	Model 7 Stainless
ESCR	Empty shell catches receiver	We.						
ESS	Extractor stems shell							
FA	Fires automatically		.500a					
FB	Follower binds		****					
FC	Fails to connect							
FCB	Fore-end cracked or broken							
FD	Follows-down				33.5 33333333333			
FF	Fails to fire							
FFP	Flat firing pin				******* *******			
FOS	Fires on safe		***************************************			3	5000	
FPHB	Firing pin hits bbl				****			
FPHI	Firing pin hits inside rim							500 500 500 500 500 500 500 500 500 500
FP0	Floor plate opens			5.50				
FPOH	Floor plate opens hard				3333333 7437 7437		200000	
FSR	Fires when safe is released							
FT	Follower tips							
GCSO	Gas cyl shot off						***************************************	
HBL	Heavy bolt lift							
HMSC	Heading mismatch-steps on case							
HPA	High pressure ammo							
HUR	Hard under rail							
JCS	Jumps cartridge						_	
JM	Jumps magazine							
JO	Jars off							
LB	Light blow							