

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 600
 GENERAL CONDITION: NEW R #: 013900
 OUTSIDE WORK: SWIVELS ADDED DATE: 7-6-72
 FROM: AL KNABBS
 FIRED AMMO TYPE: — FLEETWOOD, PA.
 & CONDITION: ASSEMBLED #18 GUN #: 96981
 PROOF: REP INSP: U TEST: _____ CODE: EP = 10/67
 HEADING: — GR./CAL.: 6 MM REM.
 BREACH OPENING: — CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

CONNECTOR-SEAR ENGAGEMENT .010 MIN. IS .020. TRIG-
GER PULL 4 POUNDS. FRONT TRIGGER ADJUSTING SCREW
BACKED OUT SO THAT TRIGGER RETRACTION IS NOT POSITIVE.
TRIGGER RUBBING LEFT SIDE OF HOUSING.

COMPLAINT: "SHELL FIRED WHEN I TOOK THE RIFLE OFF SAFETY."

INCIDENT: FOLLOW DOWN

COMMENTS: THE COMBINATION OF UNDER MIN. CONNECTOR-SEAR
ENGAGEMENT, ERRATIC RETRACTION AND SLIGHT TRIGGER
BIND, RESULT IN FOLLOW DOWN.



181
AL 0029981