

Blue Book of Gun Values
Blue Book Publications
8009 34th Avenue South #175
Minneapolis, MN 55425
800-877-GUNS
bluebookinc.com

Flayderman's Guide to Firearm Values
Gun List
Modern Gun Values
Krause Publications
700 East State Street
Iola, WI 54990-0001
847-573-8530

Gun Trader's Guide
Shooter's Guide
Stoeger Publishing Company
Mansard Court
Wayne, NJ 07470

1100 not cycling

Thank you for your inquiry. The Model 1100 is designed to shoot either 2 3/4" or 3" shells, not both. The magnum barrel has a smaller gas orifice hole and 2 3/4" shells will not produce enough pressure to cycle in the magnum barrel.

Autoloader not cycling

We apologize for any inconvenience you may be experiencing. Check to make sure that the gas orifice hole is clean and clean. Also, the magazine tube should not be lubricated. The action spring that pushes the bolt forward may need cleaning and lubricating. The stock will need to be removed for this inspection.

If you continue to have problems, we suggest taking or sending your firearm to a Remington Authorized Repair Center or our factory for evaluation.

You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state:

<http://www.remington.com/repairsvc/ModelSelection.asp>

The difference between the two are cosmetic. The Wingmaster comes with more accessories and the finishes are different. Parts between the two will interchange.