

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 660
 GENERAL CONDITION: GOOD R #: 013305
 OUTSIDE WORK: SCREWS MOUNTED, CEMENT ON DATE: 6-21-72
TRIGGER ETC. DOES NOT LOOK LIKE DUPONT. FROM: N.Y. CITY POLICE DEPT.
 FIRED AMMO TYPE: _____ BRONX, N.Y.
 & CONDITION: _____ GUN #: 125445
 PROOF: R.E.P. INSP.: 95 TEST: 13 CODE: ER = 10/68
 HEADING: O.K. GUN./CAL.: 223
 BREACH OPENING: _____ CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: 20 ROUNDS APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

CONNECTOR BROKEN, SEAR & CONNECTOR ENGAGEMENT
CORNERS BROKEN OFF. BROKEN PIECE OF CONNECTOR
SOLDERED TO TRIGGER. CONSIDERABLE RUST ETC. ON
TRIGGER & IN HOUSING. CEMENT ON SCREWS DOES NOT
HAVE THE SAME APPEARANCE AS DUPONT, USED EXCESSIVELY.
 COMPLAINT: FIRE ON CLOSING.

INCIDENT: FOLLOW DOWN.

COMMENTS: THE CUSTOMER PROBABLY EXPERIENCED PIERCED
PRIMERS WHICH BROUGHT ABOUT THE CARTRIDGE BEING
OFF AND THE BROKEN CONNECTOR



AL 0030020